




report date: 2024-03-29

General information

| | |
|---------------------|----------------------|
| Make | VOLKSWAGEN |
| Model | TOUAREG TDI SE SPORT |
| Colour | Blue |
| Year of manufacture | 2005 |
| Top speed | 111 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 174 BHP |
| Max. torque | 400 Nm at 2.000 rpm |
| Engine capacity | 2.460 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 20.8 mpg |
| Consumption extra urban | 34.9 mpg |
| Consumption combined | 28.0 mpg |
| CO2 emission | 273 g/km |
| CO2 label | M |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-07 |
| Pictures | 4 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2022-07-18 |
| MOT pass rate | 93 % |
| MOT passed | 14 |
| Failed MOT tests | 1 |
| Total advice items | 10 |
| Total items failed | 2 |

| | |
|------------------|---|
| MOT #15 | 2021-07-19 15:55 |
| MOT test number | 798470712962 |
| Result | ✓ Passed |
| Next expiry date | 2022-07-18 |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

| | |
|-----------------|------------------|
| MOT #14 | 2020-10-27 12:31 |
| MOT test number | 722660194494 |
| Result | ✓ Passed |

| | |
|-----------------|---|
| MOT #13 | 2019-04-30 09:16 |
| MOT test number | 253644972615 |
| Result | ✓ Passed |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii)) |
| Advice | Rear springs corroded |

| | |
|-----------------|------------------|
| MOT #12 | 2018-02-13 10:05 |
| MOT test number | 421007129736 |
| Result | ✓ Passed |

**MOT #11** 2017-02-17 12:56**MOT test number** 415924943551**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Front Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #10** 2016-02-16 11:00**MOT test number** 179127461590**Result** ✓ Passed**MOT #9** 2015-02-16 12:58**MOT test number** 817767145046**Result** ✓ Passed**MOT #8** 2014-02-04 13:34**MOT test number** 705225734043**Result** ✓ Passed**MOT #7** 2014-02-03 09:02**MOT test number** 125994234481**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #6** 2013-02-20 08:54**MOT test number** 259041353039**Result** ✓ Passed

**MOT #5** 2012-02-22 10:57**MOT test number** 755113552062**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2011-02-19 10:56**MOT test number** 286520251005**Result** ✓ Passed**MOT #3** 2010-02-05 10:00**MOT test number** 131606730443**Result** ✓ Passed**Advice** Brake disc slightly scored (3.5.1h)**MOT #2** 2009-02-23 15:41**MOT test number** 134154159418**Result** ✓ Passed**MOT #1** 2008-09-19 09:33**MOT test number** 634753268235**Result** ✓ Passed**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Advice** Nearside Front brake disc slightly pitted (3.5.1h)



Tax & MOT check

✕
Untaxed

Tax expired:
12 July 2022

✕
MOT

Expired:
18 July 2022

| | |
|------------------|---------------------------------|
| Tax status | Expired at 12 July 2022 |
| Days left | 658 days too late |
| MOT expiry date | 18 July 2022 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|---|
| Number of plates | 7 |
| Current registration |  ***** |
| Plate since | 2023-03-29 |
| Current registration |  ***** |
| Plate since | 2023-03-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2005-09-02 |
| Last registration | 2021-07-19 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2005-09-02 | 28 mi |
| Registration #2 | 2008-09-19 | 23.210 mi |
| Registration #3 | 2009-02-23 | 27.066 mi |
| Registration #4 | 2010-02-05 | 38.043 mi |
| Registration #5 | 2011-02-19 | 48.764 mi |
| Registration #6 | 2012-02-22 | 59.028 mi |
| Registration #7 | 2013-02-20 | 67.444 mi |
| Registration #8 | 2014-02-03 | 74.796 mi |
| Registration #9 | 2014-02-04 | 74.806 mi |
| Registration #10 | 2015-02-03 | 75.277 mi |
| Registration #11 | 2015-02-03 | 75.277 mi |
| Registration #12 | 2015-02-03 | 75.277 mi |
| Registration #13 | 2015-02-03 | 75.277 mi |
| Registration #14 | 2015-02-03 | 75.277 mi |
| Registration #15 | 2015-02-03 | 75.277 mi |
| Registration #16 | 2015-02-03 | 75.277 mi |
| Registration #17 | 2015-02-03 | 75.277 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1928 mm |
| Height | 1723 mm |
| Length | 4754 mm |
| Wheel base | 2855 mm |
| Kerb weight | 2510 kg |
| Max. allowed weight | 2850 kg |

Additional information

| | |
|-----------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | BAC 069514 |