



General information

|                     |                |
|---------------------|----------------|
| Make                | VOLKSWAGEN     |
| Model               | GOLF GT TDI    |
| Colour              | Grey           |
| Year of manufacture | 2009           |
| Top speed           | 130 mph        |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 140 BHP             |
| Max. torque             | 320 Nm at 1.750 rpm |
| Engine capacity         | 1.968 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 44.1 mpg            |
| Consumption extra urban | 70.6 mpg            |
| Consumption combined    | 57.7 mpg            |
| CO2 emission            | 129 g/km            |
| CO2 label               | D                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-02-06                  |
| Pictures      | 10                          |
| Listing price | <a href="#">View report</a> |



source: [autoonline.co.uk](#)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-05-05 |
| MOT pass rate      | 72 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 5          |
| Total advice items | 23         |
| Total items failed | 14         |

MOT #18 2024-04-08 11:44

MOT test number 506710863936

Result ✓ Passed

Next expiry date 2025-05-05

**Advice** Rear exhaust heat shield insecure but contained

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

MOT #17 2023-04-11 08:35

MOT test number 140861235190

Result ✓ Passed

**Minor** Nearside Lower Windscreen excessively tinted but not adversely affecting driver's view crack (3.2 (b) (i))

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

MOT #16 2022-04-12 08:03

MOT test number 164430932538

Result ✓ Passed

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

MOT #15 2021-05-06 11:57

MOT test number 431763813761

Result ✓ Passed

**MOT #14** 2021-03-23 10:26**MOT test number** 239210413780**Result** ✗ Failed**Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement  
inner bush chalked (5.3.4 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement  
chalked (5.3.4 (a) (i))**MOT #13** 2020-01-07 12:21**MOT test number** 802350292289**Result** ✓ Passed**MOT #12** 2020-01-06 12:23**MOT test number** 768167360437**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1  
(b) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2018-12-11 14:33**MOT test number** 512407621613**Result** ✓ Passed

**MOT #10** 2018-12-10 10:25**MOT test number** 929969490696**Result** ✗ Failed

- Fail** Nearside Front Direction indicator not working (4.4.1 (a) (ii))
- Fail** Exhaust has a major leak of exhaust gases joint of front to centre ,sleeve broken. (6.1.2 (a))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm cords showing,and flat (5.2.3 (e))
- Fail** Offside Front Service brake excessively binding pads and discs are in poor condition, due to heat. (1.2.1 (f))

**MOT #9** 2018-01-09 14:25**MOT test number** 828952311481**Result** ✓ Passed**MOT #8** 2018-01-09 11:00**MOT test number** 646489594959**Result** ✗ Failed

- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Rear tyres cracking in tread
- Fail** Nearside Front front brake binding (3.7.B.1)
- Advice** Front lower suspension arms rear bushes worn
- Advice** Rear brake discs corroded

**MOT #7** 2017-01-06 11:13**MOT test number** 562334557893**Result** ✓ Passed

**MOT #6** 2016-01-11 15:25**MOT test number** 513047550305**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2015-09-08 08:43**MOT test number** 153755827311**Result** ✓ Passed**MOT #4** 2014-09-20 12:00**MOT test number** 897333564259**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2014-09-18 13:28**MOT test number** 209761864203**Result** ✗ Failed**Fail** Nearside Front Direction indicator not working (1.4.A.2c)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



|                 |                  |
|-----------------|------------------|
| MOT #2          | 2013-09-24 13:04 |
| MOT test number | 109197563281     |
| Result          | ✓ Passed         |

|                 |   |
|-----------------|---|
| MOT #1          | 2012-09-24 11:50  |
| MOT test number | 709618362277  |
| Result          | ✓ Passed  |
| Advice          | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice          | Nearside Rear Tyre worn close to the legal limit (4.1.E.1)  |
| Advice          | Offside Front Tyre worn close to the legal limit (4.1.E.1)  |
| Advice          | Offside Rear Tyre worn close to the legal limit (4.1.E.1)   |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
5 May 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 February          |
| <b>Days left</b>        | 278                             |
| <b>MOT expiry date</b>  | 5 May 2025                      |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | D          |
| <b>Single payment (12 months)</b>              | £ 150,00,- |
| <b>Single six month payment</b>                | £ 82,50,-  |
| <b>Total payable by 12 monthly instalments</b> | £ 157,50,- |





Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>SD59ONV</b> |
| Plate since          | 2019-03-29   |
| Current registration |  <b>SD59ONV</b> |
| Plate since          | 2019-03-29   |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 20                       |
| First mileage registration | 2009-09-29               |
| Last registration          | 2024-04-08               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2009-09-29 | 11 mi     |
| Registration #2  | 2012-09-24 | 23.030 mi |
| Registration #3  | 2013-09-24 | 34.301 mi |
| Registration #4  | 2014-09-18 | 43.926 mi |
| Registration #5  | 2014-09-20 | 43.926 mi |
| Registration #6  | 2015-09-08 | 54.037 mi |
| Registration #7  | 2016-01-11 | 56.322 mi |
| Registration #8  | 2017-01-06 | 66.326 mi |
| Registration #9  | 2018-01-09 | 74.217 mi |
| Registration #10 | 2018-01-09 | 74.220 mi |
| Registration #11 | 2019-01-09 | 84.220 mi |
| Registration #12 | 2019-01-09 | 84.220 mi |
| Registration #13 | 2019-01-09 | 84.220 mi |
| Registration #14 | 2019-01-09 | 84.220 mi |
| Registration #15 | 2019-01-09 | 84.220 mi |
| Registration #16 | 2019-01-09 | 84.220 mi |
| Registration #17 | 2019-01-09 | 84.220 mi |
| Registration #18 | 2019-01-09 | 84.220 mi |
| Registration #19 | 2019-01-09 | 84.220 mi |
| Registration #20 | 2019-01-09 | 84.220 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 97%                             |
| Children       | 84%                             |
| Pedestrian     | 61%                             |
| Safety systems | 71%                             |
| Overall rating | 85%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1786 mm |
| Height              | 1479 mm |
| Length              | 4199 mm |
| Wheel base          | 2578 mm |
| Kerb weight         | 1299 kg |
| Max. allowed weight | 1910 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 55 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 3                |

|                 |            |
|-----------------|------------|
| Number of seats | 5          |
| Number of axles | 2          |
| Engine number   | CBA 494126 |