



report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 D3 SE LUX AWD
Colour	Silver
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-02-25
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-27
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	7
Total items failed	7

MOT #13 2023-06-28 08:30

MOT test number 291628540818

Result ✓ Passed

Next expiry date 2024-06-27

Advice Anti-roll bar linkage ball joint has slight play offside + nearside rear (5.3.4 (a) (i))

Advice Suspension arm pin or bush worn but not resulting in excessive movement nearside rear trailing arm bush (5.3.4 (a) (i))

MOT #12 2023-06-27 11:52

MOT test number 278867568575

Result ✗ Failed

Fail Offside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))

Advice Anti-roll bar linkage ball joint has slight play offside + nearside rear (5.3.4 (a) (i))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Suspension arm pin or bush worn but not resulting in excessive movement nearside rear trailing arm bush (5.3.4 (a) (i))

MOT #11 2022-06-10 10:46

MOT test number 788115686196

Result ✓ Passed

**MOT #10** 2022-06-10 10:46**MOT test number** 109580402083**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #9** 2021-08-09 14:03**MOT test number** 410954741290**Result** ✓ Passed**Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #8** 2021-08-09 11:02**MOT test number** 387308132854**Result** ✗ Failed**Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))**Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #7** 2020-09-09 17:11**MOT test number** 721440603597**Result** ✓ Passed**MOT #6** 2019-11-21 13:29**MOT test number** 835381818586**Result** ✓ Passed**MOT #5** 2018-09-07 15:49**MOT test number** 778915729586**Result** ✓ Passed

**MOT #4** 2018-03-12 12:24**MOT test number** 644883478251**Result** ✓ Passed**MOT #3** 2017-01-18 14:59**MOT test number** 562941891232**Result** ✓ Passed**MOT #2** 2017-01-18 14:15**MOT test number** 942238020833**Result** ✗ Failed**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #1** 2015-10-23 10:32**MOT test number** 829398482775**Result** ✓ Passed**Advice** Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
27 June 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	27 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-10-31
Last registration	2023-06-28
Complete history	See info



Registration #1	2012-10-31	13 mi
Registration #2	2015-10-23	51.241 mi
Registration #3	2017-01-18	69.194 mi
Registration #4	2017-01-18	69.194 mi
Registration #5	2018-03-12	79.340 mi
Registration #6	2018-09-07	110.346 mi
Registration #7	2019-11-21	117.251 mi
Registration #8	2020-09-09	119.026 mi
Registration #9	2020-09-09	119.026 mi
Registration #10	2020-09-09	119.026 mi
Registration #11	2020-09-09	119.026 mi
Registration #12	2020-09-09	119.026 mi
Registration #13	2020-09-09	119.026 mi
Registration #14	2020-09-09	119.026 mi
Registration #15	2020-09-09	119.026 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1891 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1133407