




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI
Colour	Silver
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption



Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1	
Date	2021-11-07
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-22
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	41
Total items failed	3

MOT #13	2024-03-20 11:07
MOT test number	248546051447
Result	✓ Passed
Next expiry date	2025-03-22
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #12**

2024-03-07 14:30

MOT test number

628015378338

Result**✗ Failed****Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))

Fail

Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #11

2023-03-14 07:57

MOT test number

980767568983

Result**✓ Passed****Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2022-03-09 08:23

MOT test number

989934594277

Result**✓ Passed****MOT #9**

2021-02-25 11:52

MOT test number

943493821689

Result**✓ Passed****Advice**

No visual or metered emissions detected.



MOT #8	2020-03-06 15:58
MOT test number	977664413867
Result	✓ Passed
Advice	Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	No visual or metered emissions detected.

MOT #7	2019-03-14 14:54
MOT test number	886165684631
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front tyres worn inner edges & perishing.
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	No visual or metered emissions detected.

MOT #6	2018-03-08 15:19
MOT test number	670333306324
Result	✓ Passed
Advice	No visual or metered emissions detected.

MOT #5	2018-03-08 09:16
MOT test number	344844898088
Result	✗ Failed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	No visual or metered emissions detected.
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Nearside Front coil spring broken (2.4.C.1a)

**MOT #4** 2017-03-16 10:08**MOT test number** 604805561953**Result** ✓ Passed**Advice** Boot seats in down position,unable to test seat belts fully.**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**Advice** No visual or metered emissions detected.**MOT #3** 2016-03-16 10:38**MOT test number** 669434920430**Result** ✓ Passed**MOT #2** 2015-03-03 09:17**MOT test number** 946922865027**Result** ✓ Passed**Notice** Rear tyres perishing between tread.**Notice** All centre row seat belts child seats fitted,unable to test fully.**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Nearside front tyre perishing between tread.**Notice** No visual or metered emissions detected.**Notice** Under-trays fitted obscuring some underside components**Notice** Offside front tyre worn badly inner edge,new recommended.



MOT #12014-03-19 10:39

MOT test number827348674007

Result

✓ Passed

- Notice

No visual or metered emissions detected.
- Notice

Wiper blades smearing slightly.
- Notice

Under-trays fitted obscuring some underside components
- Notice

Rear tyres perishing between tread.
- Notice

Child seat fitted not allowing full inspection of adult belt
- Notice

Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
22 March 2025

Tax status	Valid until 1 December
Days left	217
MOT expiry date	22 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VK11DMV
Plate since	2024-03-29
Current registration	 VK11DMV
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-22
Last registration	2024-03-20
Complete history	See info



Registration #1	2011-03-22	16 mi
Registration #2	2014-03-19	27.742 mi
Registration #3	2015-03-03	34.982 mi
Registration #4	2016-03-16	42.741 mi
Registration #5	2017-03-16	51.232 mi
Registration #6	2018-03-08	58.498 mi
Registration #7	2018-03-08	58.505 mi
Registration #8	2019-03-14	65.157 mi
Registration #9	2019-03-20	65.157 mi
Registration #10	2019-03-20	65.157 mi
Registration #11	2019-03-20	65.157 mi
Registration #12	2019-03-20	65.157 mi
Registration #13	2019-03-20	65.157 mi
Registration #14	2019-03-20	65.157 mi
Registration #15	2019-03-20	65.157 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles

2

Engine number

CAY 586764