





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN SE TSI
Colour	Silver
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	220 Nm at 1.500 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.2 mpg
CO2 emission	166 g/km
CO2 label	Н



CarCheck.co.uk page 1/14



EN10WAA
report date: 2024-03-29

Internet history

	-	-	-	-	1
ᆮ	п	ıL	Г١	,	1

LIICI Y I	
Date	2022-01-19
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2025-02-22
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	18
Total items failed	10

MOT #18	2024-01-26 14:38
MOT test number	886462901345
Result	✓ Passed
Next expiry date	2025-02-22
Advice Rear Child Seat fitted not allowing full inspection of adult belt be	oth outer rear positions n/s/r +o/s/r

MOT #17 2024-01-23 13:35 MOT test number 851250261260

Result X Failed

Fail Nearside Headlamp aim projected beam image is obviously incorrect no pattern (4.1.2 (c))

Advice Rear Child Seat fitted not allowing full inspection of adult belt both outer rear positions n/s/r +o/s/r

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure within tread area (5.2.3 (d) (ii))

Fail Offside Front Coil spring fractured or broken broken incomplete also damage to top shocker mount (5.3.1 (b) (i))

MOT #16	2023-02-10 11:30
MOT test number	930671513292
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #15

MOT test number

416101074596

Result

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Central Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #14

MOT test number

Result

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT test number
913515693273

Result

Advice
Brake disc worn, pitted or scored, but not seriously weakened Both rear (1.1.14 (a) (ii))

Advice
Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail
Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice
Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #12

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #11 2021-06-16 10:01

MOT test number 870335437259

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail
Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #10 2020-06-18 10:40

MOT test number 279544188228

Result \rightarrow Passed

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #9 2019-06-15 11:15

MOT test number 991671603897

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

MOT #8 2018-06-18 09:53

MOT test number 533368336101

Advice Nearside rearmost seat in closed position, adult seatbelt not inspected

Advice Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/14



MOT #5

EN10WAA

report date: 2024-03-29

2016-05-20 12:21

MOT #7	2018-05-26 09:46
MOT test number	716157789870
Result	✓ Passed
MOT #6	2017-05-25 08:28
MOT test number	172618752139
Result	✓ Passed
Advice Front tyres worn inner edge.	

MOT test number	643322267038
Result	✓ Passed
MOT #4	2015-05-19 11:57
MOT test number	185319835119
Result	✓ Passed
MOT #3	2014-06-04 09:48
MOT test number	395065654120

Result	\checkmark	Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2013-05-23 14:29
MOT test number	517563343133
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #1

MOT test number

695803943137

Result

Pass with rectification

Nearside Headlamp aim too far to the right (1.8)

CarCheck.co.uk page 7/14





report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 8/14



EN10WAA
report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



CarCheck.co.uk

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 9/14



EN10WAA
report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	JK UK
Plate since	800-0-0
Current registration	NK NK
Plate since	
	Mana infa
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-07-12
Last registration	2024-01-26
Complete history	See info



Registration #1	2010-07-12	15 mi
Registration #2	2013-05-23	18.979 mi
Registration #3	2014-06-04	25.559 mi
Registration #4	2015-05-19	32.639 mi
Registration #5	2016-05-20	39.952 mi
Registration #6	2017-05-25	50.326 mi
Registration #7	2018-05-26	71.863 mi
Registration #8	2018-06-18	72.083 mi
Registration #9	2019-06-15	94.155 mi
Registration #10	2020-06-18	113.858 mi
Registration #11		11.777 es
Danishashiaa #12		
Registration #12		11.117 au
Registration #13		11.777 es
		11.777 es
Registration #13		11,777 es 11,777 es 11,777 es
Registration #13 Registration #14		11,777 ea 11,777 ea 11,777 ea
Registration #13 Registration #14 Registration #15		11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #13 Registration #14 Registration #15 Registration #16		11,777 es 11,777 es 11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1524 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
0 0 1	7.4/7.4

CarCheck.co.uk page 14/14

Number of seats	7
Number of axles	2
Engine number	CAV 093461