



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	LAGUNA GT TURBO
Colour	Grey
Year of manufacture	2008
Top speed	147 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	205 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	43.4 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 2


Date	2021-07-24
Pictures	22
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-23
Pictures	22
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-04-07
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	36
Total items failed	11

MOT #16	2022-04-08 16:51
MOT test number	538044201638
Result	✓ Passed
Next expiry date	2023-04-07
Advice	Nearside Front Drive shaft damaged but serviceable (6.1.7 (e))

MOT #15	2020-11-23 13:40
MOT test number	576541579630
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14	2020-11-20 15:14
MOT test number	980745034149
Result	✗ Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13** 2019-05-01 11:33**MOT test number** 746924802879**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12** 2018-05-16 15:39**MOT test number** 738101888064**Result** ✓ Passed**Advice** FRONT WIPERS SMEARING SLIGHTLY**Advice** BOTH FRONT TOP MOUNTS SLIGHT ROUGHNESS IN BEARINGS**MOT #11** 2018-05-16 09:04**MOT test number** 102235334571**Result** ✗ Failed**Advice** FRONT WIPERS SMEARING SLIGHTLY**Advice** BOTH FRONT TOP MOUNTS SLIGHT ROUGHNESS IN BEARINGS**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #10** 2017-05-18 09:26**MOT test number** 149721759726**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 2-3mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9**

2017-05-15 09:02

MOT test number

523635355050

Result**✗ Failed****Fail** Electronic parking brake control defective so that it cannot be satisfactorily operated (3.1.3c)**Advice** Offside Front Tyre worn close to the legal limit 2-3mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc small inner clip (2.5.C.1a)**MOT #8**

2016-05-31 16:09

MOT test number

391082964127

Result**✓ Passed****Advice** Plastic covers fitted to underside.**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7**

2016-05-31 08:52

MOT test number

222146802973

Result**✗ Failed****Fail** Nearside Front Tyre has ply or cords exposed on outer tread (4.1.D.1b)**Advice** Plastic covers fitted to underside.**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside rear tyre, metal object in inner tread.**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside front tyre 2-3 mm tread depth.

**MOT #6** 2015-05-16 11:47**MOT test number** 105806535171**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Both rear tyre treads slightly distorted**MOT #5** 2015-05-16 11:47**MOT test number** 165456835193**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Notice** Both rear tyre treads slightly distorted**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-05-29 17:23**MOT test number** 937259144123**Result** ✓ Passed**Notice** Plastic covers fitted to underside.**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-05-29 12:13**MOT test number** 706269844121**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Plastic covers fitted to underside.



MOT #2	2013-02-09 10:55
MOT test number	869950343036
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Front brake pads wearing low.
Notice	Front tyres wearing low 2-3 mm tread depth.
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2011-12-21 09:55
MOT test number	806185051334
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
31 May 2023

X

MOT

Expired:
7 April 2023

Tax status	Expired at 31 May 2023
Days left	333 days too late
MOT expiry date	7 April 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-11-06
Last registration	2022-04-08
Complete history	See info



Registration #1	2008-11-06	16 mi
Registration #2	2011-12-21	23.788 mi
Registration #3	2013-02-09	34.003 mi
Registration #4	2014-05-29	46.747 mi
Registration #5	2014-05-29	46.749 mi
Registration #6	2015-05-16	56.983 mi
Registration #7	2016-05-31	67.987 mi
Registration #8	2016-05-31	67.987 mi
Registration #9	2017-05-15	82.459 mi
Registration #10	2019-05-29	95.277 mi
Registration #11	2019-05-29	95.277 mi
Registration #12	2019-05-29	95.277 mi
Registration #13	2019-05-29	95.277 mi
Registration #14	2019-05-29	95.277 mi
Registration #15	2019-05-29	95.277 mi
Registration #16	2019-05-29	95.277 mi
Registration #17	2019-05-29	95.277 mi
Registration #18	2019-05-29	95.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2060 mm
Height	1445 mm
Length	4695 mm
Wheel base	2756 mm
Max. allowed weight	2022 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

C000404