



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLS CLS320 CDI
Colour	Silver
Year of manufacture	2007
Top speed	148 mph
0 - 60 mph	7.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	27.7 mpg
CO2 emission	200 g/km
CO2 label	J



**MOT history**

MOT expiry date	2021-12-19
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	9
Total items failed	5

MOT #14 2020-12-12 10:47**MOT test number** 753771907196**Result** ✓ Passed**Next expiry date** 2021-12-19**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2019-12-20 12:05**MOT test number** 491190575021**Result** ✓ Passed**MOT #12** 2019-12-19 14:36**MOT test number** 996948591417**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**Fail** Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #11** 2018-12-20 17:37**MOT test number** 566867436395**Result** ✓ Passed**MOT #10** 2018-08-14 17:17**MOT test number** 511754787797**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2017-11-10 14:40**MOT test number** 883007949723**Result** ✓ Passed**MOT #8** 2017-11-03 15:15**MOT test number** 409271889572**Result** ✗ Failed**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Fail** Fuel system component leaking engine bay area (7.2.3)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2016-09-16 09:00**MOT test number** 251276977103**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #6** 2015-09-12 09:01**MOT test number** 934332298412**Result** ✓ Passed



MOT #5	2014-09-19 14:45
---------------	------------------

MOT test number	687562164272
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2013-09-14 10:53
---------------	------------------

MOT test number	545937453269
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2012-09-17 09:40
---------------	------------------

MOT test number	188181562271
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2011-09-12 16:39
---------------	------------------

MOT test number	329595251472
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	O/s rear driveshaft gaiter slight leak
---------------	----------------------------------------

MOT #1	2010-09-20 09:22
---------------	------------------

MOT test number	330113460216
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✖
Untaxed

Tax expired:
31 January 2021

✖
MOT

Expired:
19 December 2021

Tax status	Expired at 31 January 2021
Days left	1183 days too late
MOT expiry date	19 December 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-09-29
Last registration	2020-12-12
Complete history	See info



Registration #1	2007-09-29	9 mi
Registration #2	2010-09-20	25.324 mi
Registration #3	2011-09-12	34.945 mi
Registration #4	2012-09-17	46.647 mi
Registration #5	2013-09-14	57.385 mi
Registration #6	2014-09-19	70.599 mi
Registration #7	2015-09-12	85.405 mi
Registration #8	2016-09-16	103.274 mi
Registration #9	2017-09-20	121.143 mi
Registration #10	2018-09-24	139.012 mi
Registration #11	2019-09-28	156.881 mi
Registration #12	2020-09-30	174.750 mi
Registration #13	2021-10-04	192.619 mi
Registration #14	2022-10-08	210.488 mi
Registration #15	2023-10-12	228.357 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2059 mm
Height	1403 mm
Length	4913 mm
Wheel base	2854 mm
Kerb weight	1815 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	64292040446156