





report date: 2024-03-29

General information

Make	MINI
Model	MINI ONE
Colour	Red
Year of manufacture	2012
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



BV12XGD

report date: 2024-03-29

Internet history

Entry 3

Date	2023-03-22
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 2

Date	2023-02-11	
Pictures	5	
Listing price	<u>View report</u>	









source: cargurus.co.uk

Entry 1

Date	2021-01-21
Pictures	0
Listing price	<u>View report</u>

source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-12
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	16
Total items failed	2

MOT #11	2024-01-05 15:39
MOT test number	178786974434
Result	✓ Passed
Next expiry date	2025-01-12

MOT #10	2023-01-06 10:04
MOT test number	921528313686
Result	✓ Passed
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14)	(a) (ii))

MOT #9		2022-01-13 13:51
MOT test	number	233645099636
Result		✓ Passed
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		1.14 (a) (ii))
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		14 (a) (ii))
Advice	Service brake fluctuating, but not excessively both rears recommend replace (1.2.1 (e))

MOT #8	2020-11-13 14:59
MOT test number	833829853722
Result	✓ Passed
Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/12



(i))

BV12XGD report date: 2024-03-29

MOT #7 2019-12-03 12:38

MOT test number 673171604571

Result ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Rear child seat fitted, unable to check seatbelt

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2018-11-27 10:57

MOT test number 142978881833

Result Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing tread depth 3mm (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing tread depth 3mm (5.2.3 (d) (ii))

MOT #5 2017-11-28 11:30

MOT test number 638395119270

Result ✓ Passed

MOT #4 2017-11-21 12:17

MOT test number 540265425780

Result X Failed

Fail Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

CarCheck.co.uk page 4/12



BV12XGD

report date: 2024-03-29

MOT test number

Fesult

MOT test number

Fesult

MOT #2

MOT test number

2015-11-17 09:32

MOT test number

281228690848

Result

Advice

NEARSIDE FRONT TYRE HAS SIDEWALL DAMAGE.

MOT #1

MOT test number

Result

Notice Engine covers fitted obscuring some components in the engine bay

2014-11-25 17:17

115129524303

✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	12 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MINI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

*		
For how long did the current and previous owner(s) have this MINI? How many owners die Check it in the premium report and see all owner registrations. Download the full report is		e?

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	NK SIES	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-23
Last registration	2024-01-05
Complete history	See info



Registration #1	2012-03-23	26 mi
Registration #2	2014-11-25	18.036 mi
Registration #3	2015-11-17	21.963 mi
Registration #4	2016-11-18	28.438 mi
Registration #5	2017-11-21	36.898 mi
Registration #6	2017-11-28	37.024 mi
Registration #7	2018-11-27	40.707 mi
Registration #8	2019-12-03	44.971 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		91,700 esi
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine numberA024J283