





report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 S
Colour	Red
Year of manufacture	2007
Top speed	116 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	35.8 mpg
CO2 emission	189 g/km
CO2 label	J



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2021-11-05

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



KM07NXE report date: 2024-03-29

MOT history

MOT expiry date	2022-01-29
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	28
Total items failed	12

MOT #18		2021-01-30 16:05
MOT test n	number	223072714815
Result		✓ Passed
Next expir	ry date	2022-01-29
Advice	Offside Front Anti-lock braking system wheel speed sensor damaged but not	excessively (1.6 (c))

MOT #17	2021-01-30 16:05
MOT test number	191185025815
Result	★ Failed
Pass with rectification	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Pass with rectification Macpherson strut has an unsafe modification Bolts Loose (5.3.3 (c) (i))	
Advice Offside Front Anti-lock braking system wheel speed sensor damaged but not excessively (1.6 (c))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #16 2020-12-03 12:35

MOT test number 651847506956

Result X Failed

Fail Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Slight exhaust blow

Fail Offside Front Suspension component insecurely attached hub loose on shock absorber (5.3.3 (a) (i))

Fail Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Front Anti-lock braking system component excessively damaged abs lead broken (1.6 (e))

MOT #15 2019-08-31 14:59

MOT test number 929953443925

Result \sqrt{Passed}

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Play in steering rack inner joint(s)

Minor Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt both (2.1.3 (g) (i))

Minor Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #14 2019-08-31 14:59

MOT test number 380089461326

Result X Failed

Minor Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt both (2.1.3 (g) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Play in steering rack inner joint(s)

Minor Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Pass with rectification Stop lamp(s) all not working (4.3.1 (a) (iii))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #13 2018-07-30 08:18

MOT test number 929813843487

Result \(\sqrt{Passed} \)

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #12 2017-07-26 09:34

MOT test number 679945565619

Result
✓ Passed

MOT #11 2016-08-16 11:25

MOT test number 314453837945

MOT #10 2016-08-15 08:44

MOT test number 947583971870

Result X Failed

Fail Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Nearside Headlamp not working on dipped beam (1.7.5a)

MOT #9 2015-09-01 00:00

MOT test number 771472847276

Result ✓ Passed

MOT #8 2015-09-01 00:00

MOT test number 822286669302

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT test number

S88908754271

Result

Notice Play in steering rack inner joint(s)

Notice Rear Axle bushes deteriorated but not causing excessive play

Advice Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)

Notice Oil leak

MOT #6 2014-09-15 13:31 366008954445 **MOT** test number × Failed Result Notice Oil leak Advice Offside Front Suspension arm has slight play in a ball joint (2.4.G.2) Notice Play in steering rack inner joint(s) Pass with rectification Front Brake pad(s) less than 1.5 mm thick (3.5.1g) **Notice** Rear Axle bushes deteriorated but not causing excessive play

MOT #5		2013-09-19 10:16
MOT test	number	238112663268
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Play in steering rack inner joint(s)	
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	
Notice	Oil leak	

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #4

MOT test number

896960452267

Result

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT test number

Result

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Nearside Headlamp aim too low (1.8)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

 MOT #2
 2011-09-28 12:30

 MOT test number
 379011671245

 Result
 ✓ Passed

MOT #1

MOT test number

Result

Notice Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax expired: 30 November 2021

X MOT

Expired: 29 January 2022

Tax status	Expired at 30 November 2021
Days left	882 days too late
MOT expiry date	29 January 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

O	والمراجع والأجا
Owner	nistorv

Owner history	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	ZIS UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-04-18
Last registration	2021-01-30
Complete history	See info



Registration #1	2007-04-18	23 mi
Registration #2	2010-09-07	32.265 mi
Registration #3	2011-09-28	43.406 mi
Registration #4	2012-09-04	53.069 mi
Registration #5	2012-09-06	53.074 mi
Registration #6	2013-09-19	61.073 mi
Registration #7	2014-09-15	74.753 mi
Registration #8	2015-09-01	83.633 mi
Registration #9	2016-08-15	88.603 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1306 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/1

Number of axles 2

Engine number FX6Q3172412