



General information

|                     |                |
|---------------------|----------------|
| Make                | VOLKSWAGEN     |
| Model               | FOX            |
| Colour              | Red            |
| Year of manufacture | 2010           |
| Top speed           | 92 mph         |
| 0 - 60 mph          | 17.5 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 55 BHP              |
| Max. torque             | 108 Nm at 3.000 rpm |
| Engine capacity         | 1.198 cc            |
| Cylinders               | 3                   |
| Fuel type               | Petrol              |
| Consumption city        | 36.2 mpg            |
| Consumption extra urban | 55.4 mpg            |
| Consumption combined    | 46.3 mpg            |
| CO2 emission            | 139 g/km            |
| CO2 label               | E                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-05                  |
| Pictures      | 6                           |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk

**MOT history**

|                           |            |
|---------------------------|------------|
| <b>MOT expiry date</b>    | 2024-04-27 |
| <b>MOT pass rate</b>      | 77 %       |
| <b>MOT passed</b>         | 10         |
| <b>Failed MOT tests</b>   | 3          |
| <b>Total advice items</b> | 15         |
| <b>Total items failed</b> | 17         |

**MOT #13** 2023-04-28 12:30**MOT test number** 902460599103**Result** Passed**Next expiry date** 2024-04-27

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #12** 2021-10-05 16:17**MOT test number** 352869495209**Result** Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11** 2020-09-12 12:18**MOT test number** 389539844388**Result** Passed

**MOT #10** 2020-09-12 08:58**MOT test number** 568366757098**Result** ✗ Failed

- Fail** Brake lever has insufficient reserve travel (1.1.2 (a))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #9** 2019-09-23 13:51**MOT test number** 731366952927**Result** ✓ Passed**MOT #8** 2018-09-24 09:42**MOT test number** 415359335275**Result** ✓ Passed**MOT #7** 2017-09-11 16:11**MOT test number** 630047154864**Result** ✓ Passed

- Advice** Offside Front Tyre has a cut in it

**MOT #6** 2017-09-11 09:38**MOT test number** 616182482099**Result** ✗ Failed**Fail** Front Exhaust has a major leak of exhaust gases flexi (7.1.2)**Advice** Offside Front Tyre has a cut in it**Fail** Offside Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2016-06-23 12:05**MOT test number** 600668035192**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #4** 2016-06-20 15:46**MOT test number** 683765690952**Result** ✗ Failed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)**Fail** Nearside Front Direction indicators not working (1.4.A.2c)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Fail** Nearside Front Windscreen wiper blade insecure (8.2.2)**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #3** 2015-01-07 16:57**MOT test number** 865137105075**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #2** 2014-01-07 12:24**MOT test number** 199627204048**Result** ✓ Passed**MOT #1** 2013-01-04 16:27**MOT test number** 307324703001**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 February 2025

✗  
**MOT**  
  
Expired:  
27 April 2024

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Valid until 1 February          |
| Days left        | 278                             |
| MOT expiry date  | 27 April 2024                   |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 48         |
| Band                                    | E          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>PF59EJN</b> |
| Plate since          | 2024-03-28   |
| Current registration |  <b>PF59EJN</b> |
| Plate since          | 2024-03-28   |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

|                   |          |          |
|-------------------|----------|----------|
| Finance company   | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type    | REDACTED | REDACTED |
| Agreement term    | REDACTED | REDACTED |
| Agreement number  | REDACTED | REDACTED |
| Contact info      | REDACTED | REDACTED |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 15                       |
| First mileage registration | 2010-01-11               |
| Last registration          | 2023-04-28               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2010-01-11 | 10 mi     |
| Registration #2  | 2013-01-04 | 30.241 mi |
| Registration #3  | 2014-01-07 | 35.710 mi |
| Registration #4  | 2015-01-07 | 46.313 mi |
| Registration #5  | 2016-06-20 | 66.095 mi |
| Registration #6  | 2016-06-23 | 66.190 mi |
| Registration #7  | 2017-09-11 | 74.119 mi |
| Registration #8  | 2017-09-11 | 74.119 mi |
| Registration #9  | 2018-05-20 | 75.277 mi |
| Registration #10 | 2018-05-20 | 75.277 mi |
| Registration #11 | 2018-05-20 | 75.277 mi |
| Registration #12 | 2018-05-20 | 75.277 mi |
| Registration #13 | 2018-05-20 | 75.277 mi |
| Registration #14 | 2018-05-20 | 75.277 mi |
| Registration #15 | 2018-05-20 | 75.277 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1660 mm |
| Height              | 1544 mm |
| Length              | 3828 mm |
| Wheel base          | 2465 mm |
| Kerb weight         | 1069 kg |
| Max. allowed weight | 1480 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 3                     |

|                 |            |
|-----------------|------------|
| Number of seats | 4          |
| Number of axles | 2          |
| Engine number   | CHF 058721 |