





report date: 2024-03-28

## General information

Make	MERCEDES-BENZ
Model	SLK SLK250 CDI BLUEEFFICIENCY AMG SPORT
Colour	Silver
Year of manufacture	2014
Top speed	151 mph
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	150 kW / 204 HP / 204 BHP
Max. torque	500 Nm at 1.600 rpm
Engine capacity	2.143 сс
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	Е



CarCheck.co.uk page 1/12



Internet history

c	-	~~	1

Life y 1	
Date	2021-06-04
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT h	nistory
-------	---------

MOT expiry date	2025-04-22	
MOT pass rate	73 %	
MOT passed	8	
Failed MOT tests	3	
Total advice items	10	
Total items failed	5	

MOT #11	2024-04-23 12:34
MOT test number	261568641896
Result	✓ Passed
Next expiry date	2025-04-22

MOT #10	2024-04-23 08:17
MOT test number	317364361707
Result	<b>X</b> Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #9	2023-03-30 16:21
MOT test number	772973570407
Result	<b>✓</b> Passed

MOT #8	2022-04-20 10:40
MOT test number	705997807024
Result	<b>✓</b> Passed

MOT #7	2021-03-12 11:30
MOT test number	335411801862
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT #6** 2020-03-18 16:27

MOT test number 431168482106

**Result** ✓ Passed

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge wearing on inner edege (5.2.3 (e))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**MOT #5** 2019-03-05 16:14

MOT test number 844116242084

**Result** 
✓ Passed

MOT #4 2019-03-04 12:33

**MOT test number** 947293368751

Result X Failed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt Camber (5.3.4 (b) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

MOT #3 2018-03-06 10:35

**MOT test number** 379337363907

Result 

Passed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2 2018-03-05 13:11

MOT test number 262968154605

Result × Failed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Horn not loud enough to be heard by another road user (1.6.2b)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #1** 2017-03-01 10:53

**MOT test number** 867743555949

**Result** ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

## Tax & MOT check

Tax expired: 1 April 2024





Tax status	Expired at 1 April 2024
Days left	27 days too late
MOT expiry date	22 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

## Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1

Date

Category

Damage 2

**Type** 

**Date** 

Dailiage 2

Category

**Type** 



#### Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

## Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report <a href="https://example.com/here">here</a> .	
***************************************	
THE STATE OF THE S	
	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 9/12



## Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-13
Last registration	2024-04-23
Complete history	See info



Registration #1	2014-03-13	28 mi
Registration #2	2017-03-01	28.957 mi
Registration #3	2018-03-05	34.495 mi
Registration #4	2018-03-06	34.494 mi
Registration #5	2019-03-04	38.700 mi
Registration #6	2019-03-05	38.700 mi
Registration #7	2020-03-18	44.187 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.777 es
Registration #13		71.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

60225	Air conditionin
60295	
0482	
0501	
0566	
0567	
0569	
iew the complete MERCEDES-BENZ factory list for this	More info >

# Dimensions & weight

Width	1810 mm
Height	1301 mm
Length	4134 mm
Wheel base	2430 mm
Kerb weight	1590 kg
Max. allowed weight	1905 kg

## Additional information

· · · · · · · · · · · · · · · · · · ·	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	65198032265025

CarCheck.co.uk page 12/12