



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO S (75BHP)
Colour	Grey
Year of manufacture	2006
Top speed	104 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	126 Nm at 3.800 rpm
Engine capacity	1.400 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.2 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.2 mpg
CO2 emission	182 g/km
CO2 label	I





Internet history

Entry 2


Date	2021-07-02
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-04
Pictures	26
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-11
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	31
Total items failed	8

MOT #22 2023-07-07 10:24**MOT test number** 790387794125**Result** ✓ Passed**Next expiry date** 2024-07-11**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Cambelt due??**MOT #21** 2023-07-06 14:04**MOT test number** 300748863519**Result** ✗ Failed**MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Cambelt due??**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**MOT #20** 2022-07-11 16:54**MOT test number** 941973223372**Result** ✓ Passed

**MOT #19** 2021-07-12 17:39**MOT test number** 624537845864**Result** ✓ Passed**MOT #18** 2021-07-12 16:11**MOT test number** 426074538331**Result** ✗ Failed**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #17** 2020-10-15 11:25**MOT test number** 137431077252**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #16** 2020-10-14 10:34**MOT test number** 151583758849**Result** ✗ Failed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MAJOR** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**MAJOR** Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Offside Headlamp insecure (4.1.1 (c))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Offside Headlamp aim too high (4.1.2 (a))

**MOT #15** 2019-05-24 10:24**MOT test number** 168047582227**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2019-05-23 11:48**MOT test number** 188260895485**Result** ✗ Failed**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13** 2018-02-06 12:57**MOT test number** 274107591372**Result** ✓ Passed**Advice** Offside Rear slight binding**Advice** Oil leak gearbox**MOT #12** 2018-02-06 12:57**MOT test number** 865216691093**Result** ✗ Failed**Advice** Oil leak gearbox**Advice** Offside Rear slight binding**Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Central Exhaust system not adequately supported (7.1.1)

**MOT #11** 2017-01-30 10:02**MOT test number** 132125311102**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #10** 2017-01-30 10:02**MOT test number** 187939528112**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Pass with rectification** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #9** 2015-12-05 10:24**MOT test number** 875436445376**Result** ✓ Passed**MOT #8** 2015-12-05 10:24**MOT test number** 340073307737**Result** ✗ Failed**Pass with rectification** Registration plate lamp does not illuminate simultaneously with the position lamps (1.1.C.1a)**MOT #7** 2014-11-28 17:29**MOT test number** 919942334323**Result** ✓ Passed**MOT #6** 2013-11-06 12:20**MOT test number** 108680413380**Result** ✓ Passed



MOT #5 2013-11-05 14:55

MOT test number 265279903353

Result ✗ Failed

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #4 2012-11-24 14:19

MOT test number 929419822332

Result ✓ Passed

MOT #3 2011-12-20 18:29

MOT test number 555064351334

Result ✓ Passed

MOT #2 2010-11-01 16:02

MOT test number 593145500389

Result ✓ Passed

MOT #1 2009-09-18 11:25

MOT test number 672501169267

Result ✓ Passed

Notice Wipers smearing

Notice Handbrake req adjusting



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
11 July 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	11 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-01-01
Current registration	 XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2006-11-13
Last registration	2023-07-07
Complete history	See info



Registration #1	2006-11-13	28 mi
Registration #2	2009-09-18	10.619 mi
Registration #3	2010-11-01	15.102 mi
Registration #4	2011-12-20	20.141 mi
Registration #5	2012-11-24	26.567 mi
Registration #6	2013-11-05	31.972 mi
Registration #7	2013-11-06	31.972 mi
Registration #8	2014-11-28	39.989 mi
Registration #9	2015-12-05	44.335 mi
Registration #10	2015-12-05	44.335 mi
Registration #11	2017-01-30	48.765 mi
Registration #12	2017-01-30	48.765 mi
Registration #13	2018-02-06	52.652 mi
Registration #14	2019-05-20	55.557 mi
Registration #15	2019-05-20	55.557 mi
Registration #16	2019-05-20	55.557 mi
Registration #17	2019-05-20	55.557 mi
Registration #18	2019-05-20	55.557 mi
Registration #19	2019-05-20	55.557 mi
Registration #20	2019-05-20	55.557 mi
Registration #21	2019-05-20	55.557 mi
Registration #22	2019-05-20	55.557 mi
Registration #23	2019-05-20	55.557 mi
Registration #24	2019-05-20	55.557 mi
Registration #25	2019-05-20	55.557 mi



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1238 kg
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKY428776