



report date: 2024-03-28

General information

Make	FORD
Model	C-MAX ZETEC 136
Colour	Blue
Year of manufacture	-
Top speed	125 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-17
Pictures	11
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #17	2020-12-09 14:39
MOT test number	412263278584
Result	✓ Passed
Next expiry date	2021-12-08

MOT #16	2019-12-05 14:26
MOT test number	601431809686
Result	✓ Passed

MOT #15	2019-12-05 11:04
MOT test number	541621985537
Result	✗ Failed

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2018-12-07 14:27
MOT test number	793963232950
Result	✓ Passed

Advice Rear exhaust box has 1st skin corrosion

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Oil leak

**MOT #13**

2018-12-01 16:55

MOT test number

501273722319

Result

✗ Failed

Fail Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear exhaust box has 1st skin corrosion**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Oil leak**MOT #12**

2017-11-29 10:23

MOT test number

588885216481

Result

✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #11**

2017-11-21 15:50

MOT test number

689023401858

Result

✗ Failed

Fail Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**MOT #10**

2016-10-31 10:21

MOT test number

276494487016

Result

✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2015-10-30 16:12**MOT test number** 425767759877**Result** ✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

Advice Rear exhaust silencer outer skin deteriorating

MOT #8 2015-10-30 09:44**MOT test number** 375815637757**Result** ✗ Failed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

Advice Rear exhaust silencer outer skin deteriorating

Advice Offside Rear Tyre worn close to the legal limit 3mm worn on inner edge (4.1.E.1)

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #7 2014-10-31 16:23**MOT test number** 106564204341**Result** ✓ Passed**MOT #6** 2014-10-31 16:23**MOT test number** 645214404387**Result** ✗ Failed

Pass with rectification Offside Headlamp aim too low (1.8)

Pass with rectification Nearside Headlamp aim too low (1.8)

Pass with rectification Offside Stop lamp not working (1.2.1b)

**MOT #5** 2013-11-01 17:47**MOT test number** 436205103316**Result** ✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #4 2013-10-31 10:56**MOT test number** 496944603458**Result** ✗ Failed

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Nearside Front coil spring broken (2.4.C.1a)

Notice Offside front tyre worn on inner edge

Fail Offside Front Headlamp levelling device obviously defective (1.7.2)

MOT #3 2012-10-31 12:38**MOT test number** 109695602363**Result** ✓ Passed

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Notice Slight damage to outer side wall, nearside front tyre.

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2 2011-10-31 12:23**MOT test number** 278824201347**Result** ✓ Passed

Notice Nail in offside rear tyre



MOT #1	2011-10-31 12:23
MOT test number	106824101382
Result	✗ Failed
Notice	Nail in offside rear tyre
Pass with rectification	Nearside Headlamp aim too high (1.8)
Pass with rectification	Offside Headlamp aim too high (1.8)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EA58AWG
Plate since	2019-03-28
Current registration	EA58AWG
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-11-10
Last registration	2020-12-09
Complete history	See info



Registration #1	2008-11-10	23 mi
Registration #2	2011-10-31	43.929 mi
Registration #3	2012-10-31	57.736 mi
Registration #4	2013-10-31	71.311 mi
Registration #5	2013-11-01	71.321 mi
Registration #6	2014-10-31	85.379 mi
Registration #7	2015-10-30	96.100 mi
Registration #8	2015-10-30	96.100 mi
Registration #9	2016-10-31	107.450 mi
Registration #10	2016-10-31	107.450 mi
Registration #11	2016-10-31	107.450 mi
Registration #12	2016-10-31	107.450 mi
Registration #13	2016-10-31	107.450 mi
Registration #14	2016-10-31	107.450 mi
Registration #15	2016-10-31	107.450 mi
Registration #16	2016-10-31	107.450 mi
Registration #17	2016-10-31	107.450 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Max. allowed weight	1990 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

8G46203