




General information

Make	MINI
Model	COUNTRYMAN COOPER S ALL4A COOPER S ALL4
Colour	White
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I






## Internet history

### Entry 1

Date	2024-01-11
Pictures	40
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

MOT expiry date	2025-05-04
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	21
Total items failed	2

<b>MOT #12</b>	2024-04-12 08:19
MOT test number	721519756117
Result	✓ Passed
Next expiry date	2025-05-04

<b>MOT #11</b>	2023-05-03 11:10
MOT test number	455097940771
Result	✓ Passed
<b>Minor</b>	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

<b>MOT #10</b>	2022-05-05 16:25
MOT test number	582498435288
Result	✓ Passed
<b>Advice</b>	Rear Drive shaft joint worn, but not excessively (6.1.7 (c) (i))



<b>MOT #9</b>	2022-05-04 14:39
<b>MOT test number</b>	228932014773
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge worn to 3mm (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge worn to 3mm (5.2.3 (e))
<b>Advice</b>	Rear Drive shaft joint worn, but not excessively (6.1.7 (c) (i))
<b>Fail</b>	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge worn to 3mm (5.2.3 (e))

<b>MOT #8</b>	2021-01-21 11:08
<b>MOT test number</b>	634925714449
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2020-01-17 10:06
<b>MOT test number</b>	391732194881
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #6</b>	2018-12-29 10:32
<b>MOT test number</b>	430026882335
<b>Result</b>	✓ Passed
<b>Advice</b>	Chips in windscreen zone A and zone B
<b>Advice</b>	Screw in nearside rear tyre



MOT #5 2018-12-28 09:16

MOT test number 327423476657

Result ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Chips in windscreen zone A and zone B
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Screw in nearside rear tyre

MOT #4 2018-01-03 11:40

MOT test number 821404347083

Result ✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear tyre has cuts to inner sidewall
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Oil leak

MOT #3 2017-01-28 13:23

MOT test number 338724572274

Result ✓ Passed

MOT #2 2015-11-15 12:56

MOT test number 850842409963

Result ✓ Passed



<b>MOT #1</b>	2014-10-24 11:07
<b>MOT test number</b>	978177994221
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 April 2025

✓  
**MOT**

**Expires:**  
4 May 2025

**Tax status** Valid until 1 April

**Days left** 115

**MOT expiry date** 4 May 2025

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





**Vehicle valuation**

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	KN61RXP
Plate since	2019-09-29
Current registration	KN61RXP
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled. If not, and you buy this MINI then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MINI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >



## Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	14
<b>First mileage registration</b>	2011-11-16
<b>Last registration</b>	2024-04-12
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2011-11-16	10 mi
<b>Registration #2</b>	2014-10-24	6.060 mi
<b>Registration #3</b>	2015-11-15	10.003 mi
<b>Registration #4</b>	2017-01-28	21.939 mi
<b>Registration #5</b>	2018-01-03	27.860 mi
<b>Registration #6</b>	2018-12-28	34.950 mi
<b>Registration #7</b>	2018-12-29	34.950 mi
<b>Registration #8</b>	2019-05-01	35.277 mi
<b>Registration #9</b>	2019-05-01	35.277 mi
<b>Registration #10</b>	2019-05-01	35.277 mi
<b>Registration #11</b>	2019-05-01	35.277 mi
<b>Registration #12</b>	2019-05-01	35.277 mi
<b>Registration #13</b>	2019-05-01	35.277 mi
<b>Registration #14</b>	2019-05-01	35.277 mi

[More info >](#)

## Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

## Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



## Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Kerb weight	1405 kg
Max. allowed weight	1865 kg

## Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

---

**Engine number**

A738J098