



PEUGEOT

GR53AVK

report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 SE HDI (90BHP)
Colour	Blue
Year of manufacture	-
Top speed	111 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	205 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-31
Pictures	4
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT #26	2021-10-07 12:08
MOT test number	442031680222
Result	✓ Passed
Next expiry date	2022-11-03
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Exhaust system corroded
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

MOT #25	2020-11-04 12:23
MOT test number	947054547258
Result	✓ Passed
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #24	2020-11-04 10:20
MOT test number	835538234414
Result	✗ Failed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Fail	Offside Rear Position lamp not working (4.2.1 (a) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Fail	Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #23**

2019-10-29 17:44

MOT test number

494571617837

Result

✓ Passed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Rear exhaust box outer casing corroded**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #22**

2019-10-25 13:23

MOT test number

173868605075

Result

✗ Failed

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Rear exhaust box outer casing corroded**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21**

2018-10-18 16:17

MOT test number

320746848622

Result

✓ Passed

- Advice** Offside Side repeater slightly discoloured (4.4.3 (a))
- Advice** Exhaust front flexi in poor condition
- Advice** Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))
- Advice** Oil level low on dipstick
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #20

2018-10-18 13:30

MOT test number

311564603328

Result

✗ Failed

- Advice** Exhaust front flexi in poor condition
- Advice** Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Oil level low on dipstick
- Advice** Offside Side repeater slightly discoloured (4.4.3 (a))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

**MOT #19**

2017-11-01 14:40

MOT test number

597312627062

Result

✓ Passed

Advice

Nearside front and both side repeater indicators faded

MOT #18

2017-10-19 09:29

MOT test number

137970278334

Result

✗ Failed

Fail

Position lamp switch does not illuminate the front and rear position lamps with a single operation (1.1.A.2)

Advice

Offside Front Ball joint has slight play steering arm inner (2.2.B.1f)

Advice

Nearside front and both side repeater indicators faded

Fail

Nearside Front Ball joint has excessive play steering arm inner (2.2.B.1f)

Fail

Nearside Rear coil spring broken (2.4.C.1a)

MOT #17

2016-10-22 16:02

MOT test number

353007120469

Result

✓ Passed

Advice

Side repeater slightly discoloured Both (1.4.A.2f)

Advice

Towball/hitch not fitted at time of test

Advice

Rear coil spring corroded Both (2.4.C.1b)

Advice

Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice

Child Seat fitted not allowing full inspection of adult belt

Advice

Under trays fitted and slightly insecure (recommend attention soon)

Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #16**

2016-10-22 15:37

MOT test number

191648604094

Result**✗ Failed**

- Fail** Electrical wiring insecure Rear Tow bar socket wire (1.9.2a)
- Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Under trays fitted and slightly insecure (recommend attention soon)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Fail** Horn not working (1.6.2a)
- Advice** Side repeater slightly discoloured Both (1.4.A.2f)
- Advice** Towball/hitch not fitted at time of test
- Advice** Rear coil spring corroded Both (2.4.C.1b)

MOT #15

2015-11-04 14:01

MOT test number

150226178325

Result**✓ Passed**

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened . (3.5.1i)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened . (3.5.1i)
- Advice** Slight injector blow by

**MOT #14**

2015-11-02 08:41

MOT test number

801130290752

Result

✗ Failed

- Advice** Slight injector blow by
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened . (3.5.1i)
- Fail** Exhaust system not adequately supported (7.1.1)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened . (3.5.1i)
- Fail** Exhaust has a major leak of exhaust gases (7.1.2)

MOT #13

2014-12-22 08:41

MOT test number

666846254320

Result

✓ Passed

- Advice** Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Notice** Play in steering rack inner joint(s)
- Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Oil filler cap missing

MOT #12

2014-01-20 08:56

MOT test number

745080524018

Result

✓ Passed

- Advice** Offside Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2013-01-11 16:23**MOT test number** 855301113056**Result** ✓ Passed

Advice Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

MOT #10 2013-01-11 16:23**MOT test number** 888321213022**Result** ✗ Failed

Pass with rectification Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Advice Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

MOT #9 2012-01-12 08:36**MOT test number** 538332312097**Result** ✓ Passed

Advice Offside Ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8 2012-01-12 08:36**MOT test number** 956582112065**Result** ✗ Failed

Advice Offside Ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2011-01-15 08:40**MOT test number** 536595211063**Result** ✓ Passed**MOT #6** 2011-01-15 08:40**MOT test number** 188735711050**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2010-01-07 16:32**MOT test number** 564147900022**Result** ✓ Passed**MOT #4** 2009-01-09 15:33**MOT test number** 731969509090**Result** ✓ Passed**MOT #3** 2009-01-09 09:11**MOT test number** 333929509047**Result** ✗ Failed**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)



MOT #2	2008-01-15 17:03
MOT test number	744095618026
Result	✓ Passed
<div>Notice</div> Child seat fitted not allowing full inspection of adult belt	

MOT #1	2007-01-25 11:36
MOT test number	901785827085
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	GR53AVK
Plate since	2019-09-29
Current registration	GR53AVK
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-02-20
Last registration	2021-10-07
Complete history	See info



Registration #1	2004-02-20	15 mi
Registration #2	2007-01-25	23.234 mi
Registration #3	2008-01-15	30.788 mi
Registration #4	2009-01-09	38.201 mi
Registration #5	2009-01-09	38.201 mi
Registration #6	2010-01-07	44.708 mi
Registration #7	2011-01-15	51.350 mi
Registration #8	2012-01-12	57.661 mi
Registration #9	2013-01-11	63.378 mi
Registration #10	2014-01-20	69.364 mi
Registration #11	2014-12-22	74.462 mi
Registration #12	2015-11-02	81.801 mi
Registration #13	2015-11-04	81.801 mi
Registration #14	2016-01-20	81.801 mi
Registration #15	2016-01-20	81.801 mi
Registration #16	2016-01-20	81.801 mi
Registration #17	2016-01-20	81.801 mi
Registration #18	2016-01-20	81.801 mi
Registration #19	2016-01-20	81.801 mi
Registration #20	2016-01-20	81.801 mi
Registration #21	2016-01-20	81.801 mi
Registration #22	2016-01-20	81.801 mi
Registration #23	2016-01-20	81.801 mi
Registration #24	2016-01-20	81.801 mi
Registration #25	2016-01-20	81.801 mi



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1260 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2

Engine number	DYSA3011585
---------------	-------------