



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 2

Date	2021-11-05
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-11-04
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-29
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	1
Total items failed	13

MOT #14	2023-12-12 11:01
MOT test number	635442567248
Result	✓ Passed
Next expiry date	2024-12-29

MOT #13	2022-12-30 11:14
MOT test number	924886737341
Result	✓ Passed

MOT #12	2021-11-17 13:41
MOT test number	932849609404
Result	✓ Passed

**MOT #11**

2021-11-12 13:43

MOT test number

447203585950

Result**✗ Failed**

- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn Rear Bush (5.3.4 (a) (i))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn Rear Bush (5.3.4 (a) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #10

2020-10-22 08:41

MOT test number

631187375991

Result**✓ Passed****MOT #9**

2019-05-02 09:57

MOT test number

944968947169

Result**✓ Passed****MOT #8**

2018-03-21 11:17

MOT test number

829252930765

Result**✓ Passed**

**MOT #7** 2017-03-24 12:11**MOT test number** 789846807391**Result** ✓ Passed**MOT #6** 2017-03-21 11:17**MOT test number** 883167804685**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #5** 2016-02-18 12:23**MOT test number** 568690018623**Result** ✓ Passed**MOT #4** 2015-02-13 13:53**MOT test number** 388254945006**Result** ✓ Passed**MOT #3** 2014-02-19 10:57**MOT test number** 417540554038**Result** ✓ Passed**MOT #2** 2014-02-19 09:36**MOT test number** 938130554071**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Notice** Offside rear tyre cracking on sidewall



MOT #1	2013-03-13 14:05
MOT test number	238242873012
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
29 December 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	29 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-30
Last registration	2023-12-12
Complete history	See info



Registration #1	2010-03-30	6 mi
Registration #2	2013-03-13	27.812 mi
Registration #3	2014-02-19	31.567 mi
Registration #4	2014-02-19	31.587 mi
Registration #5	2015-02-13	40.289 mi
Registration #6	2016-02-18	53.505 mi
Registration #7	2017-03-21	65.927 mi
Registration #8	2017-03-24	65.981 mi
Registration #9	2018-03-21	77.608 mi
Registration #10	2019-03-20	89.237 mi
Registration #11	2019-03-20	89.237 mi
Registration #12	2019-03-20	89.237 mi
Registration #13	2019-03-20	89.237 mi
Registration #14	2019-03-20	89.237 mi
Registration #15	2019-03-20	89.237 mi
Registration #16	2019-03-20	89.237 mi
Registration #17	2019-03-20	89.237 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602