



HYUNDAI




report date: 2024-10-06

General information

Make	HYUNDAI
Model	SONATA CDX
Colour	Silver
Year of manufacture	2005
Top speed	126 mph
0 - 60 mph	10.4 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	160 BHP
Max. torque	219 Nm at 4.250 rpm
Engine capacity	2.359 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.0 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.1 mpg
CO2 emission	210 g/km
CO2 label	K






Internet history

Entry 2


Date	2022-11-24
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2022-11-12
Pictures	11
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2025-11-01
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	31
Total items failed	3

MOT #20 2024-10-30 13:18

MOT test number 797948652737

Result ✓ Passed

Next expiry date 2025-11-01

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Offside Rear Suspension component corroded but not seriously weakened Spring carrier arm (5.3.3 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension component corroded but not seriously weakened Spring carrier arm (5.3.3 (b) (i))

MOT #19 2023-10-26 08:38

MOT test number 668177987056

Result ✓ Passed

- Advice** Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))



MOT #18	2022-10-20 08:13
MOT test number	528323417755
Result	✓ Passed
Advice	Offside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Nail in tyre
Advice	Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))
Advice	Nearside Front Play in steering rack inner joint(s)
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #17	2021-10-22 15:51
MOT test number	707520566152
Result	✓ Passed
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #16	2021-10-21 10:00
MOT test number	283780266909
Result	✗ Failed
MAJOR	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #15	2020-10-02 15:51
MOT test number	239982155280
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))



MOT #14 2019-10-02 15:45

MOT test number 721611814397

Result ✓ Passed

MOT #13 2018-11-01 10:39

MOT test number 482704281754

Result ✓ Passed

Advice Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

Advice Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

MOT #12 2017-10-17 11:34

MOT test number 444747478304

Result ✓ Passed

MOT #11 2016-11-01 10:57

MOT test number 372446669171

Result ✓ Passed

Advice Parking brake lever has little reserve travel (3.1.6b)

MOT #10 2015-11-02 10:10

MOT test number 113043259631

Result ✓ Passed

MOT #9 2014-12-01 11:39

MOT test number 496735734459

Result ✓ Passed



MOT #8	2013-12-02 10:45
MOT test number	125266733366
Result	✓ Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7	2012-12-05 10:36
MOT test number	245450242361
Result	✓ Passed

MOT #6	2011-11-18 11:27
MOT test number	487212221436
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Both rear brake discs worn
Notice	Offside rear tyre perished

MOT #5	2010-12-10 12:26
MOT test number	334674940349
Result	✓ Passed

MOT #4	2010-12-10 12:26
MOT test number	874734240397
Result	✗ Failed
Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)



MOT #3 2009-10-01 16:07

MOT test number 853084379294

Result ✔ Passed

- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Front wiper blades poor
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2008-09-30 16:14

MOT test number 373414778244

Result ✔ Passed

MOT #1 2008-09-30 10:58

MOT test number 393394078264

Result ✘ Failed

- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Parking brake lever has no reserve travel (3.1.6b)



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
1 November 2025

Tax status Valid until 1 February

Days left 84

MOT expiry date 1 November 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	HV55NKF
Plate since	2019-09-29
Current registration	HV55NKF
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-09-30
Last registration	2024-10-30
Complete history	See info



Registration #1	2005-09-30	7 mi
Registration #2	2008-09-30	15.337 mi
Registration #3	2008-09-30	15.337 mi
Registration #4	2009-10-01	22.182 mi
Registration #5	2010-12-10	27.244 mi
Registration #6	2011-11-18	31.074 mi
Registration #7	2012-12-05	34.500 mi
Registration #8	2013-12-02	37.489 mi
Registration #9	2014-12-01	40.766 mi
Registration #10	2015-11-02	44.375 mi
Registration #11	2016-11-01	48.103 mi
Registration #12	2017-10-31	51.831 mi
Registration #13	2018-10-31	55.559 mi
Registration #14	2019-10-31	59.287 mi
Registration #15	2020-10-31	63.015 mi
Registration #16	2021-10-31	66.743 mi
Registration #17	2022-10-31	70.471 mi
Registration #18	2023-10-31	74.199 mi
Registration #19	2024-10-30	77.927 mi
Registration #20	2024-10-30	81.655 mi
Registration #21	2024-10-30	85.383 mi
Registration #22	2024-10-30	89.111 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1832 mm
Height	1475 mm
Length	4800 mm
Wheel base	2730 mm
Kerb weight	1546 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Engine number	G4KC5094077