



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI STYLE
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 1.800 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.2 mpg
CO2 emission	197 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-05-25
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-05-31
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	36
Total items failed	3

MOT #16	2022-05-24 13:26
MOT test number	361668582168
Result	✓ Passed
Next expiry date	2023-05-31
Advice	Nearside Rear Brake pad(s) wearing thin 80% worn (1.1.13 (a) (ii))
Advice	Offside Rear Brake pad(s) wearing thin 80% worn (1.1.13 (a) (ii))

MOT #15	2022-05-24 13:26
MOT test number	865121896310
Result	✗ Failed
Advice	Nearside Rear Brake pad(s) wearing thin 80% worn (1.1.13 (a) (ii))
Pass with rectification	Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Offside Rear Brake pad(s) wearing thin 80% worn (1.1.13 (a) (ii))
Pass with rectification	Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #14	2021-06-01 14:46
MOT test number	491395580374
Result	✓ Passed

**MOT #13**

2020-11-04 18:03

MOT test number

983877958509

Result

✓ Passed

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Nail in tyre**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #12**

2020-10-28 12:19

MOT test number

353689344801

Result

✗ Failed

DANGEROUS Offside Front Tyre has ply or cords exposed 235/60 R18 107V XL (5.2.3 (d) (ii))**MAJOR** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge also very heavily bald on inner edge (5.2.3 (e))**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge also very heavily bald on inner edge - about to expose cords (5.2.3 (e))**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Nail in tyre

**MOT #11**

2019-11-01 17:58

MOT test number

527029360721

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge also bald on inner edge (5.2.3 (e))**Advice** Engine covers fitted obscuring the view to some components**Advice** Offside Front Tyre worn close to legal limit/worn on edge also bald on inner edge (5.2.3 (e))**MOT #10**

2019-10-18 10:49

MOT test number

825794768365

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge also bald on inner edge (5.2.3 (e))**MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Rear Seat belt buckle missing 3rd row (7.1.2 (d))**Advice** Offside Front Tyre worn close to legal limit/worn on edge also bald on inner edge (5.2.3 (e))**MAJOR** Nearside Front Headlamp aim not tested (4.1.2 (b))**Advice** Engine covers fitted obscuring the view to some components**MOT #9**

2018-10-05 12:46

MOT test number

905880326681

Result

✓ Passed

Advice Front brake discs pitted and worn

**MOT #8** 2018-10-05 10:46**MOT test number** 991383651140**Result** ✗ Failed**MAJOR** Nearside Front Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**Advice** Front brake discs pitted and worn**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #7** 2017-10-05 09:17**MOT test number** 599888349254**Result** ✓ Passed**MOT #6** 2016-10-10 12:50**MOT test number** 467095804805**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Parking brake efficiency only just meet, 16% min.**MOT #5** 2015-09-26 10:10**MOT test number** 289743993176**Result** ✓ Passed**Advice** Child seats fitted to rear preventing full inspection of an adult seatbelt**MOT #4** 2015-09-26 10:10**MOT test number** 983422902102**Result** ✗ Failed**Advice** Child seats fitted to rear preventing full inspection of an adult seatbelt**Pass with rectification** Parking brake lever has no reserve travel (3.1.6b)



MOT #3	2015-01-05 14:16
MOT test number	825975105040
Result	✓ Passed
MOT #2	2014-09-18 10:20
MOT test number	478941164248
Result	✓ Passed
MOT #1	2013-09-19 16:39
MOT test number	398262163299
Result	✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-30
Last registration	2022-05-24
Complete history	See info



Registration #1	2010-09-30	18 mi
Registration #2	2013-09-19	26.002 mi
Registration #3	2014-09-18	35.704 mi
Registration #4	2015-01-05	38.723 mi
Registration #5	2015-09-26	45.614 mi
Registration #6	2015-09-26	45.614 mi
Registration #7	2016-10-10	60.678 mi
Registration #8	2017-10-05	69.561 mi
Registration #9	2018-10-05	76.709 mi
Registration #10	2019-05-20	85.377 mi
Registration #11	2019-05-20	85.377 mi
Registration #12	2019-05-20	85.377 mi
Registration #13	2019-05-20	85.377 mi
Registration #14	2019-05-20	85.377 mi
Registration #15	2019-05-20	85.377 mi
Registration #16	2019-05-20	85.377 mi
Registration #17	2019-05-20	85.377 mi
Registration #18	2019-05-20	85.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1946 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

D4HBAU293501