



HYUNDAI



NL62FVB


report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM SE
Colour	Black
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 3

Date	2024-03-09
Pictures	17
Listing price	View report



source: cargurus.co.uk



Entry 2

Date	2022-11-14
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 1

Date	2021-09-02
Pictures	30
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-19
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	10
Total items failed	5

MOT #13	2024-03-20 14:56
MOT test number	702594969577
Result	✓ Passed
Next expiry date	2025-03-19

MOT #12	2023-07-28 13:49
MOT test number	994463093104
Result	✓ Passed

MOT #11	2022-08-12 09:45
MOT test number	613063058640
Result	✓ Passed

MOT #10	2021-10-30 09:31
MOT test number	164996241938
Result	✓ Passed

MOT #9	2021-01-27 13:54
MOT test number	931601419181
Result	✓ Passed



MOT #8	2021-01-26 12:42
MOT test number	112592928230
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #7	2020-01-17 14:47
MOT test number	745069852770
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6	2020-01-10 09:12
MOT test number	935420750009
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5	2019-01-04 08:56
MOT test number	663665297518
Result	✓ Passed

**MOT #4** 2018-01-20 11:29**MOT test number** 342731376381**Result** ✓ Passed**MOT #3** 2018-01-19 12:52**MOT test number** 620556137276**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2017-01-25 09:19**MOT test number** 141380224676**Result** ✓ Passed**MOT #1** 2016-01-20 16:06**MOT test number** 536098664207**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
19 March 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	19 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-01-28
Last registration	2024-03-20
Complete history	See info



Registration #1	2013-01-28	26 mi
Registration #2	2016-01-20	29.138 mi
Registration #3	2017-01-25	35.837 mi
Registration #4	2018-01-19	44.664 mi
Registration #5	2018-01-20	44.666 mi
Registration #6	2019-01-04	53.773 mi
Registration #7	2020-01-10	61.762 mi
Registration #8	2020-01-17	61.868 mi
Registration #9	2021-01-26	67.505 mi
Registration #10	2022-01-20	75.277 mi
Registration #11	2022-01-20	75.277 mi
Registration #12	2022-01-20	75.277 mi
Registration #13	2022-01-20	75.277 mi
Registration #14	2022-01-20	75.277 mi
Registration #15	2022-01-20	75.277 mi
Registration #16	2022-01-20	75.277 mi
Registration #17	2022-01-20	75.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1680 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	2001 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4HBDU824233