





General information

Make	ΤΟΥΟΤΑ
Model	HILUX 280 EX MWB 4WD DCB P/U
Colour	Silver
Year of manufacture	2005
Gearbox	5 speed Manual

Engine & fuel consumption

Power	999 BHP
Max. torque	9999 Nm at 9.999 rpm
Engine capacity	2.494 сс
Cylinders	4
Fuel type	Diesel







Internet history

Entry	1

Date Pictures 2021-07-01

21

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-13
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	31
Total items failed	4

МОТ #20	2024-03-14 15:25
MOT test number	844994839583
Result	Passed
Next expiry date	2025-03-13
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear Vehicle structure or chassis corroded within 30cm of a mount	ting but not spriously
Advice Offside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security inner sill corroded, in front of chassis mounting point (6.2.2 (d) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #19	2023-02-27 16:28
MOT test number	570134650133
Result	✓ Passed





MOT #18	2	2022-01-14 08:43
MOT test	number	999705144518
Result		✓ Passed
Advice (b))	Offside Front Headlamp has a product on the lens but not seriously reducing light	output (4.1.4
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Offside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.1	1 (c))
Advice (b))		
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Offside Rear Outer Brake pipe corroded, covered in grease or other material (1.1.1	.1 (c))

MOT #17	2021-01-18 16:03
MOT test number	525149910402
Result	✓ Passed
Advice Nearside Rear lamp lens slight damage	
Advice Rear Brake pipe corroded, covered in grease or other material pipes from brake laden valve corroded (1.1.11 (c))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn outer edge	(5.2.3 (e))

MOT #16	2021-01-12 15:42
MOT test number	943505357144
Result	🗙 Failed
Advice Rear Brake pipe corroded, covered in grease or other material pipes from corroded (1.1.11 (c))	n brake laden valve
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn outer edge (5.2.3 (e))	
MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
Advice Nearside Rear lamp lens slight damage	





MOT #15		2019-12-03 14:13
MOT test	number	657781667494
Result		✓ Passed
Advice	Wipers poor	
Advice	Brake pipe corroded, covered in grease or other material at load valve (1.1.11 (5))
MOT #14		2018-11-30 14:12

	2010-11-30 14.12
MOT test number	906728032793
Result	✓ Passed
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #13	2017-12-01 12:50
MOT test number	395070281269
Result	✓ Passed

MOT #12	2016-11-30 16:01
MOT test number	811970890454
Result	✓ Passed
Advice Offside Front tyre inner sidewall perished	

MOT #11	2015-12-02 16:34
MOT test number	995999486462
Result	✓ Passed





МОТ #10	2015-11-30 11:45	
MOT test number	845835828227	
Result	🗙 Failed	
Fail Offside rear brake binding (3.7.B.1)		
FailOffside Outer Front constant velocity joint gaiter damaged to the extent that it no longer preventsthe ingress of dirt etc (2.5.C.1a)		
Fail Exhaust has a major leak of exhaust gases silencer (7.1.2)		
MOT #9	2014-12-03 14:26	
MOT test number 245017234325		
Result	✓ Passed	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)		

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8	2013-11-21 10:20
MOT test number	627005723383
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #7	2012-11-02 10:38
MOT test number	609117602374
Result	✓ Passed

МОТ #6	2011-11-03 14:45
MOT test number	675277101354
Result	✓ Passed
Advice Tyre worn close to the legal limit (4.1.E.1)	
Notice NSF & OSR wheel bearings have slight play.	





MOT #5		2011-02-16 11:35
MOT test	number	977287541059
Result		✓ Passed
Advice	Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Notice	Front bump lose	
Advice	Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Rear Leaf spring has slight wear in a shackle pin and/or bush (2.4.B.2)	

MOT #4	2010-03-04 11:25
MOT test number	563663960055
Result	✓ Passed

MOT #3	2009-02-27 09:57
MOT test number	864438959039
Result	✓ Passed

MOT #2	2009-02-27 09:57
MOT test number	552488659011
Result	× Failed
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2008-02-22 10:44
MOT test number	202103458007
Result	✓ Passed



Tax & MOT check







Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	ET
Category		LAMP
Туре		
Damage 2		AMPL
	F	A A A A A A A A A A A A A A A A A A A
Date		1º
Category		SMT.
Туре		

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-01
Last registration	2024-03-14
Complete history	See info



Registration #1	2005-03-01	21 mi
Registration #2	2008-02-22	37.071 mi
Registration #3	2009-02-27	50.671 mi
Registration #4	2010-03-04	57.813 mi
Registration #5	2011-02-16	60.777 mi
Registration #6	2011-11-03	62.465 mi
Registration #7	2012-11-02	65.634 mi
Registration #8	2013-11-21	69.208 mi
Registration #9	2014-12-03	72.266 mi
Registration #10	2015-11-30	75.519 mi
Registration #11	2015-12-02	75.519 mi
Registration #12		11.777 est
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.117 est
Registration #21		11.277 esi

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	1700 mm
Height	1785 mm
Length	4785 mm
Kerb weight	1715 kg
Max. allowed weight	2780 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	2KD1303893