





General information

Make	RENAULT
Model	CAPTUR DYNAMIQUE NAV DCI
Colour	Blue
Year of manufacture	2018
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	70.6 mpg
Consumption extra urban	83.1 mpg
Consumption combined	78.5 mpg
CO2 emission	95 g/km
CO2 label	А







Internet history


Entry 3

Date

Pictures

2023-12-12

8



source: g3remarketing.co.uk

Entry 2	
Date	2022-02-09
Pictures	38
Listing price	View report



source: autotrader.co.uk

Entry 1	
Date	2021-07-01
Pictures	37
Listing price	<u>View report</u>



source: autotrader.co.uk









MOT history

MOT expiry date	2025-03-13
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	15
Total items failed	0

MOT #6	2024-03-08 15:18
MOT test number	791355914662
Result	✓ Passed
Next expiry date	2025-03-13

MOT #5	2024-03-08 09:48
MOT test numbe	er 510650904608
Result	× Failed
DANGEROUS	Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
DANGEROUS	Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #4	2023-03-03 09:39
MOT test number	934008253084
Result	✓ Passed
MOT #3	2022-03-14 15:04
MOT test number	982497693706

✓ Passed





MOT #2		2021-04-23 09:03
MOT test	number	944455248856
Result		✓ Passed
Minor a little gre	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorate ease (6.1.7 (g) (i))	ed small split loosing
Advice adjustmer	Parking brake efficiency only just met on offside. it would appear that the bra nt or repair.	king system requires
Advice	Brake pedal wearing smooth (1.1.2 (c))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))	

MOT #1		2021-04-23 08:22
MOT test	number	258507988516
Result		🗙 Failed
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Brake pedal wearing smooth (1.1.2 (c))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor a little gre	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorat ease (6.1.7 (g) (i))	ed small split loosing
Advice adjustme	Parking brake efficiency only just met on offside. it would appear that the brant or repair.	aking system requires
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Offside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



Tax & MOT check

√ Taxed	√ MOT
Tax due: 1 March 2025	Expires: 13 March 2025
Tax status	Valid until 1 March
Days left	306
MOT expiry date	13 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4 ARAPE
Туре	
Damage 2	AMPL
	F Store
Date	1. E
Category	ame
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second se	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	
Reduction a	
Plane anna	
Current registration	
Current registration Plate since	





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-04-30
Last registration	2024-03-08
Complete history	See info



Registration #1	2018-04-30	18 mi
Registration #2	2021-04-23	71.195 mi
Registration #3	2021-04-23	71.195 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >





Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
\$0567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	79%
Pedestrian	61%
Safety systems	81%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1778 mm
Height	1566 mm
Length	4122 mm
Wheel base	2606 mm
Kerb weight	1178 kg
Max. allowed weight	1755 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	D410865