



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM SE
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-10-23
Pictures	23
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-25
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	9
Total items failed	1

MOT #10	2023-07-28 10:47
MOT test number	236247208176
Result	✓ Passed
Next expiry date	2024-08-25
Minor	Windscreen damaged but not adversely affecting driver's view just under 40mm (3.2 (a) (i))
Advice	Tyre worn close to legal limit/worn on edge Fronts (5.2.3 (e))

MOT #9	2022-08-26 12:36
MOT test number	568559605056
Result	✓ Passed

MOT #8	2022-08-22 10:29
MOT test number	667213037913
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
DANGEROUS	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #7	2021-08-24 14:14
MOT test number	524007571090
Result	✓ Passed

**MOT #6** 2021-08-23 09:38**MOT test number** 564459219834**Result** ✗ Failed**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2020-08-25 15:12**MOT test number** 221686426308**Result** ✓ Passed**MOT #4** 2020-01-09 10:01**MOT test number** 497341056043**Result** ✓ Passed**MOT #3** 2019-01-09 11:52**MOT test number** 210716784925**Result** ✓ Passed**MOT #2** 2017-11-10 13:37**MOT test number** 381717501034**Result** ✓ Passed**Advice** Nearside Front Side repeater lamp broken/cracked but not effecting operation.**MOT #1** 2017-11-10 12:10**MOT test number** 373211001037**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Front Side repeater lamp broken/cracked but not effecting operation.



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
25 August 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	25 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-12-31
Last registration	2023-07-28
Complete history	See info



Registration #1	2014-12-31	29 mi
Registration #2	2017-11-10	22.380 mi
Registration #3	2017-11-10	22.380 mi
Registration #4	2019-01-09	33.822 mi
Registration #5	2020-01-09	42.558 mi
Registration #6	2020-08-25	45.896 mi
Registration #7	2023-07-28	45.896 mi
Registration #8	2023-07-28	45.896 mi
Registration #9	2023-07-28	45.896 mi
Registration #10	2023-07-28	45.896 mi
Registration #11	2023-07-28	45.896 mi
Registration #12	2023-07-28	45.896 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1690 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	2001 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4HBEU978607