





report date: 2024-03-28

### General information

Make	BMW
Model	435 XDRIVE30D
Colour	White
Year of manufacture	2014
Top speed	130 mph
0 - 60 mph	7.5 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	245 BHP
Max. torque	540 Nm at 3.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	42.2 mpg
Consumption combined	38.2 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/11



DL64OKU report date: 2024-03-28

# Internet history

#### Entry 3

Date 2023-05-06

Pictures 28

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2022-11-10
------	------------

Pictures 28

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1

Date 2021-06-18


Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-06-22
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	8
Total items failed	0

MOT #10	2023-06-20 09:33
MOT test number	244625616341
Result	✓ Passed
Next expiry date	2024-06-22

MOT #9	2022-06-13 08:48
MOT test number	901602424479
Result	<b>✓</b> Passed

MOT #8	2021-06-23 10:41
MOT test number	208632521768
Result	✓ Passed

**MOT test number** 891270047565

**Result** X Failed

MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner face corroded and pitted (1.1.14 (a) (ii))

**DANGEROUS** Tyre has a bulge, caused by separation or partial failure of its structure both rear inner sidewall (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #6 2020-11-04 09:12

**MOT test number** 708132156780

MOT #5 2019-11-15 15:32

**MOT test number** 591522463290

**Result** 
✓ Passed

Advice Offside Play in steering rack inner joint(s) small amount of free play in o/s rack end

MOT #4 2019-11-14 13:15

**MOT test number** 727840665025

**Result** X Failed

Advice Offside Play in steering rack inner joint(s) small amount of free play in o/s rack end

**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #3 2019-05-09 12:08

**MOT test number** 208006970954

**Result** ✓ Passed

MOT #2 2018-12-10 14:43

**MOT test number** 722535050063

**Result** ✓ Passed

**MOT #1** 2017-11-16 16:32

MOT test number 205982734130

Result 

Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	22 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



DL64OKU report date: 2024-03-28

Owner history

e union motory		
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>		
***************************************		
***************************************		
	More info >	
Plate changes  See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	UK W	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-12-12
Last registration	2023-06-20
Complete history	See info



Registration #1	2014-12-12	12 mi
Registration #2	2017-11-16	22.834 mi
Registration #3	2018-12-10	28.993 mi
Registration #4	2019-05-09	31.000 mi
Registration #5	2019-11-14	41.356 mi
Registration #6	2019-11-15	41.357 mi
Registration #7	2020-11-04	52.159 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 10/11



DL64OKU report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

## Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1983 mm
Height	1690 mm
Length	4877 mm
Wheel base	2933 mm
Max. allowed weight	2675 kg

## Additional information

·	
Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	20327382 page 11/11