



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	C C200 KOMPRESSOR AVANTGARDE
Colour	Silver
Year of manufacture	2002
Top speed	142 mph
0 - 60 mph	9.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	229 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.1 mpg
Consumption extra urban	40.4 mpg
Consumption combined	30.7 mpg
CO2 emission	227 g/km
CO2 label	L





## MOT history

MOT expiry date	2020-10-19
MOT pass rate	57 %
MOT passed	13
Failed MOT tests	10
Total advice items	42
Total items failed	26

MOT #23	2019-10-16 14:33
MOT test number	446365492946
Result	✓ Passed
Next expiry date	2020-10-19

MOT #22	2019-10-15 14:22
MOT test number	750636610301
Result	✗ Failed
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
MAJOR	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #21	2018-10-20 11:36
MOT test number	954665950465
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #20** 2018-10-20 11:36**MOT test number** 306055783544**Result** ✗ Failed**Pass with rectification** Nearside Front Anti-roll bar linkage likely to become detached (5.3.3 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Front Anti-roll bar linkage likely to become detached (5.3.3 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #19** 2017-10-12 14:34**MOT test number** 827836398039**Result** ✓ Passed**MOT #18** 2017-10-12 14:34**MOT test number** 959300402549**Result** ✗ Failed**Pass with rectification** Nearside Rear coil spring broken (2.4.C.1a)**MOT #17** 2016-10-14 10:47**MOT test number** 552710541569**Result** ✓ Passed**Advice** Engine management light is on.

**MOT #16**

2016-10-06 09:26

**MOT test number**

793865515924

**Result****✗ Failed**

- Fail** Nearside Front Front wheel bearing has excessive play (2.5.A.3c)
- Fail** Offside Front Steering system has excessive free play detected at the steering wheel (steering rack fitted) tie rod end (2.2.A.1b)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front Front wheel bearing has excessive play (2.5.A.3c)
- Advice** Nearside Rear Nail in tyre non repairable.
- Advice** Engine management light is on.
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #15**

2015-10-08 08:00

**MOT test number**

471719860737

**Result****✓ Passed**

- Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)

**MOT #14**

2015-10-06 12:15

**MOT test number**

402209001464

**Result****✗ Failed****Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Offside Rear Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Nearside Rear Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #13**

2014-09-17 10:05

**MOT test number**

467610864268

**Result****✓ Passed****Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)**Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)**MOT #12**

2014-09-16 15:09

**MOT test number**

337809554255

**Result****✗ Failed****Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

**MOT #11** 2013-09-05 11:01**MOT test number** 318388343292**Result** ✓ Passed**MOT #10** 2013-09-04 14:37**MOT test number** 726117743264**Result** ✗ Failed

- Notice** Engine management light illuminated
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2012-09-04 13:34**MOT test number** 339538742266**Result** ✓ Passed

- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #8** 2012-09-04 09:05**MOT test number** 167498242281**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #7** 2011-08-31 09:52**MOT test number** 797153041250**Result** ✓ Passed**Notice** N/s/f/tyre side wall damaged but still o.k**MOT #6** 2010-01-14 15:09**MOT test number** 523064710079**Result** ✓ Passed**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**MOT #5** 2009-12-22 10:47**MOT test number** 404696359455**Result** ✗ Failed**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Fail** Offside Rear Parking brake recording little or no effort (3.7.D.3a)**MOT #4** 2008-11-12 13:52**MOT test number** 860957718326**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2008-11-12 11:58**MOT test number** 353587618325**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**MOT #2** 2007-09-18 13:48**MOT test number** 964791267276**Result** ✓ Passed**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**MOT #1** 2006-08-23 14:46**MOT test number** 400325436252**Result** ✓ Passed





Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>LK52VWF</b>
Plate since	2019-06-29
Current registration	 <b>LK52VWF</b>
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2002-12-19
Last registration	2019-10-16
Complete history	<a href="#">See info</a>



Registration #1	2002-12-19	24 mi
Registration #2	2006-08-23	50.798 mi
Registration #3	2007-09-18	60.613 mi
Registration #4	2008-11-12	71.862 mi
Registration #5	2008-11-12	71.862 mi
Registration #6	2009-12-22	86.103 mi
Registration #7	2010-01-14	86.114 mi
Registration #8	2011-08-31	105.337 mi
Registration #9	2012-09-04	116.825 mi
Registration #10	2012-09-04	116.826 mi
Registration #11	2013-09-04	129.576 mi
Registration #12	2013-09-05	129.578 mi
Registration #13	2019-10-16	129.578 mi
Registration #14	2019-10-16	129.578 mi
Registration #15	2019-10-16	129.578 mi
Registration #16	2019-10-16	129.578 mi
Registration #17	2019-10-16	129.578 mi
Registration #18	2019-10-16	129.578 mi
Registration #19	2019-10-16	129.578 mi
Registration #20	2019-10-16	129.578 mi
Registration #21	2019-10-16	129.578 mi
Registration #22	2019-10-16	129.578 mi
Registration #23	2019-10-16	129.578 mi
Registration #24	2019-10-16	129.578 mi

More info >



Dimensions & weight

Width	1727 mm
Height	1422 mm
Length	4521 mm
Wheel base	2715 mm
Kerb weight	1490 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	11195532355458