





report date: 2024-03-28

### General information

Make	CITROEN
Model	C5 E-HDI AIRDREAM VTR PLUS EGS
Colour	Grey
Year of manufacture	2013
Gearbox	6 speed Semi-Automatic

# Engine & fuel consumption

Power	113 BHP
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/13



# Internet history

### Entry 1

Date 2021-06-17

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-06-26
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	23
Total items failed	0

MOT #10	2023-06-27 13:18
MOT test number	934759412815
Result	<b>✓</b> Passed
Next expiry date	2024-06-26

MOT #9		2023-06-16 15:03
MOT test	number	627269229915
Result		<b>X</b> Failed
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
<b>MAJOR</b> Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
MAJOR Nearside Windscreen wiper missing whole arm and blade missing (3.4 (a))		
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #8	2022-03-31 08:06
MOT test number	899544853438
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



**MOT #7** 2022-03-30 10:50

MOT test number 878525444258

**Result** X Failed

**DANGEROUS** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #6 2020-12-04 11:34

MOT test number 589624606293

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



MOT #5 2019-12-10 16:18

**MOT test number** 878249214254

Result \rightarrow Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Rear Nail in tyre

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2018-12-05 09:48

**MOT test number** 388944329992

**Result** ✓ Passed

MOT #3 2017-12-14 10:35

**MOT test number** 729039437301

**Result** ✓ Passed

MOT #2 2017-05-15 12:32

MOT test number 982409321781

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



MOT #1 2016-04-21 14:45

**MOT test number** 215131617209

CarCheck.co.uk page 6/13



# Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	26 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



AO13LLE

report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this CITROEN? How many owners did this CIT have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a> .	ROEN
*********	
***************************************	
20000000	
***************************************	
More info	>
Plate changes	
See in this check if this CITROEN had different number plates.	

See in this check if this crittoen had different flumber plates.

More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-05-20
Last registration	2023-06-27
Complete history	See info



Registration #1	2013-05-20	24 mi
Registration #2	2016-04-21	12.936 mi
Registration #3	2017-05-15	21.487 mi
Registration #4	2017-12-14	25.493 mi
Registration #5	2018-12-05	32.903 mi
Registration #6	2019-12-10	38.634 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		10.777 es

More info >

CarCheck.co.uk page 12/13



### Safety ratings

NCAP rating	****
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	see crash video



# Dimensions & weight

Width	1860 mm
Height	1483 mm
Length	4829 mm
Wheel base	2815 mm
Kerb weight	1540 kg
Max. allowed weight	2174 kg

### Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	JBEG3098573

CarCheck.co.uk page 13/13