



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	407 HDI SW SPORT
Colour	Black
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-19
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-02
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	34
Total items failed	11

MOT #16	2024-02-28 16:52
MOT test number	837556514208
Result	✓ Passed
Next expiry date	2025-03-02
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Bald on edges, 205/60R15 92V (5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #15	2023-03-03 15:35
MOT test number	794444649629
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14** 2023-02-22 14:36**MOT test number** 845754728163**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**MOT #13** 2021-12-07 14:48**MOT test number** 254715722904**Result** ✓ Passed**MOT #12** 2020-11-10 16:53**MOT test number** 403783030424**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #11** 2020-11-10 12:50**MOT test number** 830275119370**Result** ✗ Failed

- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #10 2019-04-18 11:37**MOT test number** 311713722629**Result** ✓ Passed

- Advice** Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

MOT #9 2019-04-18 11:37**MOT test number** 122795994978**Result** ✗ Failed

- Advice** Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))

**MOT #8**

2018-05-14 12:40

MOT test number

460704395954

Result

✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Undertrays fitted not allowing inspection of brake/fuel lines**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Service indicator showing that the vehicle is due a service**MOT #7**

2018-05-14 10:55

MOT test number

631207030394

Result

✗ Failed

Advice Undertrays fitted not allowing inspection of brake/fuel lines**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Service indicator showing that the vehicle is due a service**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #6**

2017-05-12 11:11

MOT test number

280250316577

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front both tyres worn low on inner edge

**MOT #5** 2016-05-11 09:37**MOT test number** 535895632732**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #4** 2015-05-14 11:19**MOT test number** 698974935138**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #3** 2014-05-08 10:17**MOT test number** 386108324133**Result** ✓ Passed**Notice** O/s/f tyre worn to around 3-4mm - wearing on the inner edge**Notice** N/s/f tyre 3mm**Notice** Front brake pads worn to around 3mm**Notice** Rear brake disc's slightly corroded**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #2** 2013-05-10 15:08**MOT test number** 755760933195**Result** ✓ Passed**MOT #1** 2012-05-03 10:43**MOT test number** 587244622187**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
2 March 2025

Tax status	Valid until 1 May
Days left	2
MOT expiry date	2 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KN09JWY
Plate since	2024-03-29
Current registration	KN09JWY
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	18
First mileage registration	2009-05-15
Last registration	2024-02-28
Complete history	See info



Registration #1	2009-05-15	9 mi
Registration #2	2012-05-03	29.325 mi
Registration #3	2013-05-10	36.327 mi
Registration #4	2014-05-08	42.874 mi
Registration #5	2015-05-14	48.153 mi
Registration #6	2016-05-11	54.198 mi
Registration #7	2017-05-12	59.089 mi
Registration #8	2018-05-14	62.931 mi
Registration #9	2018-05-14	62.931 mi
Registration #10	2019-05-20	65.277 mi
Registration #11	2019-05-20	65.277 mi
Registration #12	2019-05-20	65.277 mi
Registration #13	2019-05-20	65.277 mi
Registration #14	2019-05-20	65.277 mi
Registration #15	2019-05-20	65.277 mi
Registration #16	2019-05-20	65.277 mi
Registration #17	2019-05-20	65.277 mi
Registration #18	2019-05-20	65.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1811 mm
Height	1494 mm
Length	4763 mm
Wheel base	2725 mm
Kerb weight	1612 kg
Max. allowed weight	2195 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

DYXH4040250