






### General information

| Make                | NISSAN            |
|---------------------|-------------------|
| Model               | MICRA IG-T ACENTA |
| Colour              | Orange            |
| Year of manufacture | 2018              |
| Top speed           | 109 mph           |
| 0 - 60 mph          | 12.1 seconds      |
| Gearbox             | 5 speed Manual    |

### Engine & fuel consumption

| Power                   | 89 BHP              |
|-------------------------|---------------------|
| Max. torque             | 140 Nm at 2.250 rpm |
| Engine capacity         | 898 cc              |
| Cylinders               | 3                   |
| Fuel type               | Petrol              |
| Consumption city        | 50.4 mpg            |
| Consumption extra urban | 76.3 mpg            |
| Consumption combined    | 64.2 mpg            |
| CO2 emission            | 99 g/km             |
| CO2 label               | A                   |







# Internet history


Entry 2

Date

Pictures


2023-12-12

8



#### source: g3remarketing.co.uk

| Entry 1       |                    |
|---------------|--------------------|
| Date          | 2021-07-02         |
| Pictures      | 42                 |
| Listing price | <u>View report</u> |









source: cargurus.co.uk



# MOT history

| MOT expiry date    | 2025-02-09 |
|--------------------|------------|
| MOT pass rate      | 80 %       |
| MOT passed         | 4          |
| Failed MOT tests   | 1          |
| Total advice items | 4          |
| Total items failed | 1          |

| MOT #5           | 2024-02-05 09:47 |
|------------------|------------------|
| MOT test number  | 773497952342     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-02-09       |

| MOT #4          | 2023-01-27 08:41 |
|-----------------|------------------|
| MOT test number | 792380843901     |
| Result          | ✓ Passed         |

| MOT #3   |                                                                             | 2022-01-24 09:27 |
|----------|-----------------------------------------------------------------------------|------------------|
| MOT test | number                                                                      | 630829370215     |
| Result   |                                                                             | ✓ Passed         |
| Advice   | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                  |
| Advice   | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))   |                  |
| Advice   | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |
| Advice   | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                  |

| MOT #2          | 2021-02-10 09:29 |
|-----------------|------------------|
| MOT test number | 659184240360     |
| Result          | ✓ Passed         |





| MOT #1                                                                  | 2021-02-09 12:19 |
|-------------------------------------------------------------------------|------------------|
| MOT test number                                                         | 434378155895     |
| Result                                                                  | 🗙 Failed         |
| Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) |                  |



Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 August 2024 | ✓<br>MOT<br>Expires:<br>9 February 2025 |
|-----------------------------------------|-----------------------------------------|
| Tax status                              | Valid until 1 August                    |
| Days left                               | 94                                      |
| MOT expiry date                         | 9 February 2025                         |
| Full MOT history                        | See MOT history                         |

# Tax calculation

| Vehicle class                 | 48         |
|-------------------------------|------------|
| Band                          | E          |
| First licence fee (12 months) | £ 165,00,- |
| Standard rate (12 months)     | £ 180,00,- |
| Standard rate (6 months)      | £ 99,00,-  |
| Premium rate (12 months)      | £ 570,00,- |
| Premium rate (6 months)       | £ 313,50,- |





### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |       |
|----------|-------|
| Date     | FEIDO |
| Category | Lamp  |
| Туре     |       |
| Damage 2 | VAMPL |
| Date     |       |
| Category | AMP   |
| Туре     |       |

#### Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx                                                      |             |
|---------------------------------------------------------------|-------------|
| ***********                                                   |             |
| ********                                                      |             |
| *******                                                       |             |
| ***********                                                   |             |
| ********                                                      |             |
|                                                               | More info > |
| Plate changes                                                 |             |
| See in this check if this NISSAN had different number plates. |             |
| Number of plates                                              | ,           |
| Current registration                                          |             |
| Plate since                                                   |             |
| Carrent registration                                          |             |
| Plate since                                                   |             |
|                                                               | More info > |





### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 





# Mileage check

| Odometer                   | In miles        |
|----------------------------|-----------------|
| Mileage registrations      | 7               |
| First mileage registration | 2018-03-12      |
| Last registration          | 2024-02-05      |
| Complete history           | <u>See info</u> |



| Registration #1 | 2018-03-12 | 15 mi      |
|-----------------|------------|------------|
| Registration #2 | 2021-02-09 | 2.331 mi   |
| Registration #3 | 2021-02-10 | 2.331 mi   |
| Registration #4 |            | 11.117 esi |
| Registration #5 |            | 11.117 mi  |
| Registration #6 |            | 11.117 esi |
| Registration #7 |            | 11.777 esi |

More info >





# Car features

| S0225  | Air conditioning |
|--------|------------------|
| \$0295 |                  |
| 50482  |                  |
| \$0501 |                  |
| \$0566 |                  |
| S0567  |                  |
| S0569  |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 91%             |
| Children       | 79%             |
| Pedestrian     | 79%             |
| Safety systems | 72%             |
| Overall rating | 82%             |
| Video          | see crash video |



| Dimensions & weight               |                       |
|-----------------------------------|-----------------------|
| Width                             | 1743 mm               |
| Height                            | 1455 mm               |
| Length                            | 3999 mm               |
| Wheel base                        | 2525 mm               |
| Kerb weight                       | 1068 kg               |
| Max. allowed weight               | 1530 kg               |
| Additional information            |                       |
| Fuel tank capacity                | 41                    |
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 5                     |
| Number of seats<br>CarCheck.co.uk | 5 page 11/11          |