




report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO 16V DYNAMIC SPORT
Colour	Grey
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	11.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	125 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	47.1 mpg
CO2 emission	142 g/km
CO2 label	F





MOT history

MOT expiry date	2022-04-22
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	22
Total items failed	25

MOT #19 2022-04-29 12:08

MOT test number 784588706430

Result	Failed
<b>Fail</b> Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
<b>Fail</b> Windscreen washer provides insufficient washer liquid (3.5 (a))	
<b>Fail</b> Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
<b>Fail</b> Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
<b>Fail</b> Exhaust has a major leak of exhaust gases (6.1.2 (a))	
<b>Fail</b> Suspension arm pin or bush excessively worn both front (5.3.4 (a) (i))	
<b>Advice</b> Oil leak, but not excessive (8.4.1 (a) (i))	
<b>Fail</b> Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
<b>Fail</b> Position lamp not working both front (4.2.1 (a) (ii))	
<b>Fail</b> Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
<b>Fail</b> Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	



**MOT #18** 2021-04-23 09:39

**MOT test number** 179077104990

**Result** ✔ Passed

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17** 2020-02-26 11:44

**MOT test number** 151882476729

**Result** ✔ Passed

**Advice** Lower plastic sill covers fitted/not allowing full inspection

**Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge and 1.8mm/2mm tread (5.2.3 (e))

**Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))

**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))



<b>MOT #16</b>	2020-02-24 12:44
<b>MOT test number</b>	418629217651
<b>Result</b>	✗ Failed
<b>Fail</b>	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both lights (4.7.1 (b) (ii))
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Fail</b>	Front Inner Brake disc significantly and obviously worn both sides/worn/badly corroded (1.1.14 (a) (i))
<b>Advice</b>	Nearside Rear Outer Tyre worn close to legal limit/worn on edge and 1.8mm/2mm tread (5.2.3 (e))
<b>Advice</b>	Rear Coil spring corroded both sides (5.3.1 (b) (i))
<b>Advice</b>	Lower plastic sill covers fitted/not allowing full inspection
<b>Fail</b>	Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Fail</b>	Front Exhaust has a major leak of exhaust gases front joint/gasket (6.1.2 (a))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))
<b>Advice</b>	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

<b>MOT #15</b>	2019-02-14 11:51
<b>MOT test number</b>	998161357454
<b>Result</b>	✓ Passed

<b>MOT #14</b>	2019-02-12 15:19
<b>MOT test number</b>	939520456979
<b>Result</b>	✗ Failed
<b>Fail</b>	Front Exhaust has a major leak of exhaust gases to centre / gasket (6.1.2 (a))
<b>Fail</b>	Nearside Front Brake pad(s) worn down to wear indicator wire broken (1.1.13 (a) (i))
<b>Fail</b>	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))



MOT #13 2018-02-06 09:33

MOT test number 291119016790

Result ✓ Passed

MOT #12 2018-02-06 09:33

MOT test number 730670919039

Result ✗ Failed

**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)

MOT #11 2017-03-01 09:01

MOT test number 520121470163

Result ✓ Passed

MOT #10 2017-02-28 09:39

MOT test number 276690072625

Result ✗ Failed

**Fail** Offside Headlamp aim too high (1.8)

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**Fail** Nearside Headlamp aim too high (1.8)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #9 2016-03-04 14:09

MOT test number 521293791447

Result ✓ Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



<b>MOT #8</b>	2016-03-03 12:14
<b>MOT test number</b>	608406050896
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f)
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Fail</b>	Nearside Stop lamp not working (1.2.1b)
<b>Fail</b>	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

<b>MOT #7</b>	2015-02-24 14:38
<b>MOT test number</b>	157495655069
<b>Result</b>	✓ Passed
<b>Notice</b>	Surface corrosion on rear springs
<b>Advice</b>	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

<b>MOT #6</b>	2014-03-04 16:08
<b>MOT test number</b>	985783864051
<b>Result</b>	✓ Passed

<b>MOT #5</b>	2013-04-02 17:22
<b>MOT test number</b>	185252393422
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2012-04-17 16:10
<b>MOT test number</b>	449948902175
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2011-12-02 11:10
<b>MOT test number</b>	746016331382
<b>Result</b>	✓ Passed



**MOT #2** 2011-08-16 13:19

**MOT test number** 745478221279

**Result** ✓ Passed

**MOT #1** 2010-09-02 16:13

**MOT test number** 711615640230

**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)




Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>WK57GWG</b>
Plate since	2024-03-28
Current registration	<b>WK57GWG</b>
Plate since	2024-03-28

More info >



**Finance check**

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-10
Last registration	2022-04-29
Complete history	<a href="#">See info</a>



Registration #1	2007-09-10	17 mi
Registration #2	2010-09-02	10.102 mi
Registration #3	2011-08-16	13.145 mi
Registration #4	2011-12-02	13.909 mi
Registration #5	2012-04-17	15.150 mi
Registration #6	2013-04-02	21.907 mi
Registration #7	2014-03-04	29.387 mi
Registration #8	2015-02-24	39.344 mi
Registration #9	2016-03-03	49.706 mi
Registration #10	2016-03-04	49.707 mi
Registration #11	2016-03-04	50.000 mi
Registration #12	2016-03-04	50.000 mi
Registration #13	2016-03-04	50.000 mi
Registration #14	2016-03-04	50.000 mi
Registration #15	2016-03-04	50.000 mi
Registration #16	2016-03-04	50.000 mi
Registration #17	2016-03-04	50.000 mi
Registration #18	2016-03-04	50.000 mi
Registration #19	2016-03-04	50.000 mi
Registration #20	2016-03-04	50.000 mi

[More info >](#)



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1060 kg
Max. allowed weight	2635 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1134831