




report date: 2024-03-29

General information

Make	CITROEN
Model	C-CROSSER HDI EXCLUSIVE
Colour	Grey
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	379 Nm at 2.000 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	194 g/km
CO2 label	J






Internet history

Entry 1

Date	2022-05-18
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-30
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	37
Total items failed	4

MOT #14	2023-05-23 14:52
MOT test number	119473239405
Result	✓ Passed
Next expiry date	2024-05-30
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2023-05-23 09:13
MOT test number	944077900143
Result	✗ Failed
Fail	Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2022-05-31 08:57
MOT test number	645039071605
Result	✓ Passed

**MOT #11** 2022-05-30 11:38**MOT test number** 563373143188**Result** ✗ Failed**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))**Fail** Nearside Rear Brake pipe excessively corroded and offside rear (1.1.11 (c))**MOT #10** 2021-03-10 11:39**MOT test number** 899119710861**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Suspension components corroded**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material Multiple (1.1.11 (c))**MOT #9** 2020-03-21 12:40**MOT test number** 966460961070**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #8** 2019-03-01 09:13**MOT test number** 141852876369**Result** ✓ Passed



MOT #7	2018-03-14 13:31
MOT test number	928971669238
Result	✓ Passed
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #6	2017-03-20 11:19
MOT test number	816627353977
Result	✓ Passed
Advice	Nearside Front Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
Advice	Corrosion to some underbody components and panels
Advice	Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
Advice	Front TYRES NEARLY WORN SMOOTH outside prescribed measured area
Advice	Towball/hitch not fitted at time of test
Advice	Rearmost passenger seats not fitted at time of inspection
Advice	Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)
Advice	Undercarriage trays / sill guards / splash guards / heat shields /engine covers / component covers obscuring / limiting access to prescribed areas and or items

MOT #5	2016-03-18 09:54
MOT test number	335022411025
Result	✓ Passed

**MOT #4**

2015-03-16 09:32

MOT test number

976135575002

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Engine / component covers obscuring some components in the engine bay
- Notice** Rearmost seats not fitted at time of test
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear brake fluctuating, but not excessively (3.7.B.3)
- Notice** Under-trays / heat shields obscuring some underside components
- Notice** Light corrosion to underbody compnents

MOT #3

2014-03-20 16:31

MOT test number

235579874075

Result

✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #2

2013-03-18 11:02

MOT test number

606477373067

Result

✓ Passed

- Notice** Nearside front tyre wearing inside edge
- Notice** Nearside rear tyre sidewall cracking/perishing
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Offside rear tyre sidewall cracking/perishing
- Advice** Parking brake lever has little reserve travel (3.1.6b)



MOT #1	2012-03-14 16:25
MOT test number	219464772095
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
30 May 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	30 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXX XX
Plate since	2024-03-29
Current registration	XXXX XX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-20
Last registration	2023-05-23
Complete history	See info



Registration #1	2009-03-20	15 mi
Registration #2	2012-03-14	35.322 mi
Registration #3	2013-03-18	43.948 mi
Registration #4	2014-03-20	51.377 mi
Registration #5	2015-03-16	57.343 mi
Registration #6	2016-03-18	63.301 mi
Registration #7	2017-03-20	68.667 mi
Registration #8	2018-03-14	75.766 mi
Registration #9	2019-03-20	82.865 mi
Registration #10	2020-03-16	89.964 mi
Registration #11	2021-03-18	97.063 mi
Registration #12	2022-03-20	104.162 mi
Registration #13	2023-03-14	111.261 mi
Registration #14	2024-03-16	118.360 mi
Registration #15	2025-03-18	125.459 mi
Registration #16	2026-03-20	132.558 mi

More info >



Dimensions & weight

Width	1805 mm
Height	1715 mm
Length	4645 mm
Wheel base	2670 mm
Kerb weight	1750 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DZ694008020