



report date: 2024-03-29

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G







Internet history

Entry 2


Date	2021-07-03
Pictures	30
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-07-01
Pictures	30
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-19
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	23
Total items failed	15

MOT #20 2024-02-20 14:46

MOT test number 333673524367

Result ✓ Passed

Next expiry date 2025-02-19

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #19 2024-02-20 14:46

MOT test number 169739208133

Result ✗ Failed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))
- Pass with rectification** Fuel pipe insecure front to rear (6.1.3 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #18** 2023-05-04 11:38**MOT test number** 738650636130**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #17** 2023-05-02 10:10**MOT test number** 434176375491**Result** ✗ Failed**Fail** Fuel system component leaking excessively or a risk of fire number 4 injector area (6.1.3 (b) (ii))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge heavily worn on edges (5.2.3 (e))**Minor** Offside Front Tyre obviously under inflated (5.2.3 (l))**Fail** Nearside Rear Inner Tyre has ply or cords exposed 225/50/17 (5.2.3 (d) (ii))**Fail** Offside Headlamp aim unable to be tested (4.1.2 (b))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #16** 2022-05-09 08:16**MOT test number** 282018785100**Result** ✓ Passed**MOT #15** 2021-03-20 12:37**MOT test number** 247377036056**Result** ✓ Passed

**MOT #14** 2021-03-10 10:46**MOT test number** 165878160224**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Exhaust mounting defective (6.1.2 (a))**MOT #13** 2020-03-11 12:11**MOT test number** 791514439999**Result** ✓ Passed**MOT #12** 2019-03-22 12:17**MOT test number** 849787702691**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #11** 2019-03-21 17:42**MOT test number** 230154478877**Result** ✗ Failed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10** 2018-09-07 15:31**MOT test number** 169433638544**Result** ✓ Passed

**MOT #9** 2018-09-06 15:19**MOT test number** 851342281107**Result** ✗ Failed**Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**MOT #8** 2017-09-14 11:43**MOT test number** 800670328325**Result** ✓ Passed**MOT #7** 2016-09-14 12:58**MOT test number** 617288908100**Result** ✓ Passed**Advice** Rear both rear tyres deteriorating & tread wearing low**MOT #6** 2016-09-14 09:08**MOT test number** 724210733218**Result** ✗ Failed**Advice** Rear both rear tyres deteriorating & tread wearing low**Fail** Nearside Front Tyre has ply or cords exposed around outer shoulder (4.1.D.1b)**MOT #5** 2015-09-11 09:17**MOT test number** 663579576473**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #4** 2014-09-16 14:28**MOT test number** 287709654279**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Nail in nearside rear tyre**MOT #3** 2014-09-16 13:07**MOT test number** 458539654254**Result** ✗ Failed**Notice** Nail in nearside rear tyre**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**MOT #2** 2013-09-12 10:08**MOT test number** 146675253267**Result** ✓ Passed**MOT #1** 2013-09-11 13:07**MOT test number** 148554153200**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
19 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	19 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2010-03-09
Last registration	2024-02-20
Complete history	<a href="#">See info</a>



Registration #1	2010-03-09	27 mi
Registration #2	2013-09-11	39.533 mi
Registration #3	2013-09-12	39.564 mi
Registration #4	2014-09-16	48.334 mi
Registration #5	2014-09-16	48.341 mi
Registration #6	2015-09-11	56.864 mi
Registration #7	2016-09-14	64.379 mi
Registration #8	2016-09-14	64.379 mi
Registration #9	2017-09-14	71.994 mi
Registration #10	2018-09-06	78.487 mi
Registration #11	2018-09-07	78.509 mi
Registration #12	2019-03-21	81.239 mi
Registration #13	2019-03-21	81.239 mi
Registration #14	2019-03-21	81.239 mi
Registration #15	2019-03-21	81.239 mi
Registration #16	2019-03-21	81.239 mi
Registration #17	2019-03-21	81.239 mi
Registration #18	2019-03-21	81.239 mi
Registration #19	2019-03-21	81.239 mi
Registration #20	2019-03-21	81.239 mi
Registration #21	2019-03-21	81.239 mi
Registration #22	2019-03-21	81.239 mi
Registration #23	2019-03-21	81.239 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

**Engine number**

AU21080