

Ford



## General information

Make	FORD
Model	FOCUS C-MAX ZETEC
Colour	Silver
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	113 BHP
Max. torque	155 Nm at 4.150 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg





# MOT history

MOT #14	2021-03-10 08:47
MOT test number	433831471398
Result	✓ Passed
Next expiry date	2022-03-19

MOT #13	2020-03-20 15:24
MOT test number	192054607804
Result	✓ Passed
Advice Oil leak, but not excessive from gear box (8.4.1 (a) (i))	
Advice Gearbox mounting defective	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #12	2019-03-16 12:25
MOT test number	327807588626
Result	✓ Passed

MOT #11		2018-03-15 13:21
MOT test number		458567786172
Result		✓ Passed
Advice Nearside	Headlamp deteriorated but light output not reduced (1.7.5a)	
Advice Underbod	ly surface corrosion	
Advice Offside He	eadlamp deteriorated but light output not reduced (1.7.5a)	





MOT #10	2018-03-15 12:37
MOT test number	387666184175
Result	🗙 Failed
Advice Nearside Headlamp deteriorated but light output not reduced (1.7.5a)	
Advice Underbody surface corrosion	
Fail Nearside Stop lamp not working (1.2.1b)	
Advice Offside Headlamp deteriorated but light output not reduced (1.7.5a)	
Fail Offside Stop lamp not working (1.2.1b)	

MOT #9	2017-01-30 12	:40
MOT test	<b>number</b> 4217431981	.02
Result	V Pass	sed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)	

MOT #8		2016-02-19 13:01
MOT test	number	311796467127
Result		✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Body has slight corrosion under (6.1.B.2)	

MOT #7	2015-01-24 13:43	
MOT test number	505834725070	
Result	✓ Passed	
Advice Nearside Front Direction indicator slightly discol	oured (1.4.A.2f)	
<b>Advice</b> Offside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)		
<b>Advice</b> Nearside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)		
<b>Notice</b> Child seat fitted not allowing full inspection of ac	lult belt	





MOT #6	2014-02-04 12:13
MOT test number	285655634000
Result	✓ Passed
MOT #5	2013-02-11 11:49
MOT test number	889552243068
Result	✓ Passed
MOT #4	2012-01-24 13:30
MOT test number	576874922062
Result	✓ Passed
MOT #3	2011-02-19 11:05
MOT test number	856890451020
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #2	2010-02-19 14:15
MOT test number	361280950019
Result	✓ Passed
MOT #1	2008-09-15 11:05

Result

Passed





### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
*******	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Carrent registration	
Plate since	





### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2005-08-11
Last registration	2021-03-10
Complete history	<u>See info</u>



Registration #1	2005-08-11	9 mi
Registration #2	2008-09-15	22.700 mi
Registration #3	2010-02-19	32.492 mi
Registration #4	2011-02-19	39.704 mi
Registration #5	2012-01-24	46.138 mi
Registration #6	2013-02-11	52.532 mi
Registration #7	2014-02-04	58.553 mi
Registration #8	2015-01-24	63.807 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 mi





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1825 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1371 kg
Max. allowed weight	1870 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10/10

Number of axles	2
Engine number	5R43462