



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI S/S ECOFLEX
Colour	Blue
Year of manufacture	2013
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	126 g/km
CO2 label	D





MOT history

MOT expiry date	2020-10-14
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	0
Total items failed	7

MOT #7 2020-10-06 13:50

MOT test number 287048690503

Result ✗ Failed

- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

MOT #6 2019-10-14 13:39

MOT test number 559523693436

Result ✓ Passed

MOT #5 2019-10-08 13:08

MOT test number 165408091176

Result ✗ Failed

- Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))



MOT #4	2018-09-24 11:00
---------------	------------------

MOT test number	537685539368
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2017-09-28 12:52
---------------	------------------

MOT test number	584827349875
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2016-10-04 12:59
---------------	------------------

MOT test number	148454891604
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2016-10-03 10:55
---------------	------------------

MOT test number	663342675563
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Rear Shock absorber has a serious fluid leak (2.7.3)
-------------	---



Tax & MOT check

✕
Untaxed

Tax expired:
1 November 2020

✕
MOT

Expired:
14 October 2020

Tax status	Expired at 1 November 2020
Days left	1275 days too late
MOT expiry date	14 October 2020
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2013-10-15
Last registration	2020-10-06
Complete history	See info



Registration #1	2013-10-15	26 mi
Registration #2	2016-10-03	46.176 mi
Registration #3	2016-10-04	46.176 mi
Registration #4	2017-09-28	60.949 mi
Registration #5	2019-10-20	75.277 mi
Registration #6	2019-10-20	75.277 mi
Registration #7	2019-10-20	75.277 mi
Registration #8	2020-10-06	75.277 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1270 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005128357 LN9