



HYUNDAI



AVI4TYP


report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 CRDI ACTIVE BLUE DRIVE
Colour	Silver
Year of manufacture	2014
Top speed	125 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 2


Date	2021-07-30
Pictures	42
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-05
Pictures	31
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-04-04
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	12
Total items failed	8

MOT #10	2024-04-05 13:48
MOT test number	334683497122
Result	✓ Passed
Next expiry date	2025-04-04
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Emissions too lean to record
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Noise from crank pulley area

**MOT #9** 2024-04-05 09:24**MOT test number** 717728726489**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Brake fluid low**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Emissions too lean to record**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #8** 2022-08-03 13:25**MOT test number** 745518868529**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**MOT #7** 2022-08-03 13:25**MOT test number** 378003924495**Result** ✗ Failed**Advice** Items removed from driver's view prior to test**Pass with rectification** Windscreen washer not working (3.5 (a))

**MOT #6** 2021-07-30 10:24**MOT test number** 616644623651**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material both rear (1.1.11 (c))**MOT #5** 2020-05-15 08:59**MOT test number** 502261544173**Result** ✓ Passed**MOT #4** 2020-05-15 08:59**MOT test number** 909413254647**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #3** 2019-05-15 07:51**MOT test number** 895689095999**Result** ✓ Passed**MOT #2** 2018-05-30 14:08**MOT test number** 898483294144**Result** ✓ Passed**MOT #1** 2017-06-05 10:23**MOT test number** 287553346713**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
4 April 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-06-07
Last registration	2024-04-05
Complete history	See info



Registration #1	2014-06-07	21 mi
Registration #2	2017-06-05	29.356 mi
Registration #3	2018-05-30	34.200 mi
Registration #4	2019-05-15	38.725 mi
Registration #5	2020-05-15	43.616 mi
Registration #6	2020-05-15	43.616 mi
Registration #7	2020-05-15	43.616 mi
Registration #8	2020-05-15	43.616 mi
Registration #9	2020-05-15	43.616 mi
Registration #10	2020-05-15	43.616 mi
Registration #11	2020-05-15	43.616 mi
Registration #12	2020-05-15	43.616 mi
Registration #13	2020-05-15	43.616 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4740 mm
Wheel base	2770 mm
Kerb weight	1610 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	D4FDEU451939