



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 V70 D5 SE
Colour	Black
Year of manufacture	2005
Top speed	130 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg
CO2 emission	209 g/km
CO2 label	K







Internet history

Entry 1

Date	2021-07-31
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-11-09
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	13
Total items failed	9

MOT #18	2022-11-10 13:42
MOT test number	853000682624
Result	✓ Passed
Next expiry date	2023-11-09

MOT #17	2022-11-08 14:57
MOT test number	962170948930
Result	✗ Failed
Fail	Nearside Rear Hydraulic brake calliper inadequately mounted retaining clip missing (1.1.16 (c) (i))
Fail	Central Exhaust system insecure banging on body (6.1.2 (a))
Fail	Nearside Upper Engine mounting bracket excessively loose stabilizer bolt missing (6.1.8 (a) (ii))
Fail	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
Fail	Rear Exhaust silencer insecure back box mounting bracket snapped (8.1.1 (b) (i))

MOT #16	2020-10-09 12:13
MOT test number	350677503587
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2020-10-09 08:27**MOT test number** 912419313436**Result** ✗ Failed**Fail** Offside Headlamp lens seriously defective (4.1.1 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2019-04-26 10:59**MOT test number** 508677037414**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2019-04-25 09:05**MOT test number** 287978104222**Result** ✗ Failed**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-04-20 11:59**MOT test number** 904526758563**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #11** 2017-04-11 10:29**MOT test number** 330506314469**Result** ✓ Passed**MOT #10** 2016-04-20 08:20**MOT test number** 966681975586**Result** ✓ Passed**MOT #9** 2015-04-27 11:27**MOT test number** 307657315182**Result** ✓ Passed**Advice** Offside Inner Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Inner Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**MOT #8** 2015-04-27 08:56**MOT test number** 336887715110**Result** ✗ Failed**Advice** Nearside Inner Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Inner Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)**MOT #7** 2014-04-24 09:10**MOT test number** 776454814158**Result** ✓ Passed**MOT #6** 2013-04-18 13:59**MOT test number** 829408203114**Result** ✓ Passed



MOT #5	2012-05-22 09:48
MOT test number	247823742412
Result	✓ Passed
MOT #4	2011-05-10 12:44
MOT test number	306990431131
Result	✓ Passed
MOT #3	2010-04-07 10:33
MOT test number	561427190038
Result	✓ Passed
MOT #2	2009-04-22 13:32
MOT test number	561522219171
Result	✓ Passed
MOT #1	2008-05-19 14:34
MOT test number	572630948141
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	BT05PXW
Plate since	2019-03-28
Current registration	BT05PXW
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-05-31
Last registration	2022-11-10
Complete history	See info



Registration #1	2005-05-31	18 mi
Registration #2	2008-05-19	44.896 mi
Registration #3	2009-04-22	54.655 mi
Registration #4	2010-04-07	67.477 mi
Registration #5	2011-05-10	80.379 mi
Registration #6	2012-05-22	89.205 mi
Registration #7	2013-04-18	102.749 mi
Registration #8	2014-04-24	114.667 mi
Registration #9	2015-04-27	127.272 mi
Registration #10	2015-04-27	127.272 mi
Registration #11	2016-05-20	131.277 mi
Registration #12	2017-05-20	131.277 mi
Registration #13	2018-05-20	131.277 mi
Registration #14	2019-05-20	131.277 mi
Registration #15	2020-05-20	131.277 mi
Registration #16	2021-05-20	131.277 mi
Registration #17	2022-05-20	131.277 mi
Registration #18	2023-05-20	131.277 mi
Registration #19	2024-05-20	131.277 mi
Registration #20	2025-05-20	131.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1400 mm
Length	4520 mm
Wheel base	2560 mm
Kerb weight	1427 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	291390