



report date: 2024-03-29

General information

Make	VOLVO
Model	V40 T2 R-DESIGN
Colour	Black
Year of manufacture	2017
Top speed	118 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	220 Nm at 1.100 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

Entry 2

Date	2021-08-08
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-07-22
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-16
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	16
Total items failed	2

MOT #5	2023-10-17 13:13
MOT test number	145985988102
Result	✓ Passed
Next expiry date	2024-10-16
Advice	Nearside Front Seat belt retract slowly
Advice	Steering noisy, but operates o.k
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Outer Drive shaft joint constant velocity boot has evidence of grease externally, no holes found & is secure
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4**

2023-10-06 08:40

MOT test number

410634214179

Result**✗ Failed****Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Seat belt retract slowly**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Steering noisy, but operates o.k**Fail** Offside Front Seat belt not functioning as intended Belt does not come out or retract(stuck) (7.1.2 (c))**Advice** Offside Front Outer Drive shaft joint constant velocity boot has evidence of grease externally, no holes found & is secure**MOT #3**

2022-09-10 11:19

MOT test number

931316382211

Result**✓ Passed****Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))**Advice** Under body tray fitted obscuring some testable items**MOT #2**

2021-08-13 08:01

MOT test number

226917917789

Result**✓ Passed**



MOT #12020-11-05 11:04

MOT test number685892472153

Result

✓ Passed

- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Engine cover/s fitted obscuring some components in the engine bay.
- Advice

Under tray/s fitted obscuring some underside components.



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
16 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	16 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-12-29
Last registration	2023-10-17
Complete history	See info



Registration #1	2017-12-29	10 mi
Registration #2	2020-11-05	23.076 mi
Registration #3	2022-05-20	25.277 mi
Registration #4	2022-05-20	25.277 mi
Registration #5	2022-05-20	25.277 mi
Registration #6	2022-05-20	25.277 mi
Registration #7	2022-05-20	25.277 mi
Registration #8	2022-05-20	25.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1457 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2032759