



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | VOLKSWAGEN |
| Model | BEETLE LUNA 8V |
| Colour | Silver |
| Year of manufacture | 2006 |
| Top speed | 111 mph |
| 0 - 60 mph | 11.6 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 102 BHP |
| Max. torque | 147 Nm at 3.800 rpm |
| Engine capacity | 1.596 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 26.9 mpg |
| Consumption extra urban | 47.1 mpg |
| Consumption combined | 36.7 mpg |
| CO2 emission | 185 g/km |
| CO2 label | I |






Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-09-10 |
| Pictures | 38 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-09 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-12 |
| MOT pass rate | 83 % |
| MOT passed | 15 |
| Failed MOT tests | 3 |
| Total advice items | 6 |
| Total items failed | 6 |

MOT #18 2023-09-05 09:27

MOT test number 327835181288

Result ✓ Passed

Next expiry date 2024-09-12

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #17 2022-09-02 15:26

MOT test number 819454792544

Result ✓ Passed

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #16 2022-09-01 10:11

MOT test number 958668674908

Result ✗ Failed

Fail Nearside Rear Vehicle structure has excessive corrosion which adversely affects braking or steering outer sill (6.1.1 (c) (ii))

Fail Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced outer sill (6.1.1 (c) (i))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #15** 2021-09-13 15:17**MOT test number** 459658342336**Result** ✓ Passed**MOT #14** 2021-09-10 16:16**MOT test number** 559792294242**Result** ✗ Failed

Fail Offside Rear Coil spring corroded so that its cross sectional area is reduced and seriously weakened (5.3.1 (b) (i))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #13 2021-02-17 10:55**MOT test number** 985604626682**Result** ✓ Passed**MOT #12** 2020-02-10 13:44**MOT test number** 486714374664**Result** ✓ Passed**MOT #11** 2020-02-10 10:09**MOT test number** 569882330943**Result** ✗ Failed

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #10 2019-02-20 13:47**MOT test number** 233941958109**Result** ✓ Passed



| | |
|---------------|------------------|
| MOT #9 | 2018-02-13 14:30 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 577270756549 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #8 | 2017-02-16 10:55 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 357043221427 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|--|
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |
|---------------|--|

| | |
|---------------|------------------|
| MOT #7 | 2016-02-17 08:57 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 757306905686 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #6 | 2015-02-18 13:33 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 648919745032 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #5 | 2014-02-14 09:36 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 376565244051 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #4 | 2013-02-07 10:58 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 906468033018 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #3 | 2012-02-22 10:34 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 207863152073 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|



| | |
|-----------------|------------------|
| MOT #2 | 2011-02-23 10:56 |
| MOT test number | 675664151092 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2009-09-10 17:38 |
| MOT test number | 761313359291 |
| Result | ✓ Passed |

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
12 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 187 |
| MOT expiry date | 12 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  XXXXXX |
| Plate since | 2024-03-28 |
| Current registration |  XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2006-09-11 |
| Last registration | 2023-09-05 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2006-09-11 | 9 mi |
| Registration #2 | 2009-09-10 | 21.734 mi |
| Registration #3 | 2011-02-23 | 30.818 mi |
| Registration #4 | 2012-02-22 | 40.968 mi |
| Registration #5 | 2013-02-07 | 48.593 mi |
| Registration #6 | 2014-02-14 | 54.844 mi |
| Registration #7 | 2015-02-18 | 60.703 mi |
| Registration #8 | 2016-02-17 | 65.720 mi |
| Registration #9 | 2017-02-16 | 73.802 mi |
| Registration #10 | 2018-02-13 | 81.774 mi |
| Registration #11 | 2019-02-20 | 88.646 mi |
| Registration #12 | 2020-02-19 | 95.518 mi |
| Registration #13 | 2021-02-18 | 102.390 mi |
| Registration #14 | 2022-02-17 | 109.262 mi |
| Registration #15 | 2023-02-16 | 116.134 mi |
| Registration #16 | 2024-02-15 | 123.006 mi |
| Registration #17 | 2025-02-14 | 129.878 mi |
| Registration #18 | 2026-02-13 | 136.750 mi |
| Registration #19 | 2027-02-12 | 143.622 mi |
| Registration #20 | 2028-02-11 | 150.494 mi |
| Registration #21 | 2029-02-10 | 157.366 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1724 mm |
| Height | 1502 mm |
| Length | 4081 mm |
| Wheel base | 2515 mm |
| Kerb weight | 1314 kg |
| Max. allowed weight | 1680 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |

| | |
|-----------------|------------|
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | BFS 051011 |