





report date: 2024-03-28

General information

Make	VOLVO	
Model	XC60 T5 INSCRIPTION AWD	
Colour	Grey	
Year of manufacture	2018	
Top speed	137 mph	
0 - 60 mph	6.4 seconds	
Gearbox	8 speed automatic	

Engine & fuel consumption

Power	246 BHP
Max. torque	350 Nm at 1.800 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.2 mpg
CO2 emission	173 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date 2022-03-01

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date 2022-02-16

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-07
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #5	2024-03-08 16:27
MOT test number	350492685561
Result	✓ Passed
Next expiry date	2025-03-07
Advice Child Seat fitted not allowing full inspection of adult belt	

MOT #4	2024-03-07 09:34
MOT test number	111896763130
Result	X Failed
Fail Front Outer Tyre has ply or cords exposed both side (5.2.3 (d) (ii))	
Advice Child Seat fitted not allowing full inspection of adult belt	
Advice Rear Tyre slightly damaged/cracking or perishing both side (5.2.3 (d) (ii))	
Minor Windscreen wiper blade defective (3.4 (b) (i))	

MOT #3		2023-02-23 09:38
MOT test	number	758788823879
Result		✓ Passed
Advice	Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))	
Advice	Front Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))

Advice Front Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))

MOT #1

MOT test number

Result

Advice Heater unit

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	7 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
First licence fee (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-12-17
Last registration	2024-03-08
Complete history	See info



Registration #1	2018-12-17	19 mi
Registration #2	2021-11-24	31.704 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		D.777 es
Registration #6		11.777 es
Registration #7		D.777 es
Registration #8		11.117 es

More info >

CarCheck.co.uk page 10/11




report date: 2024-03-28

Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	98%
Children	87%
Pedestrian	76%
Safety systems	95%
Overall rating	90%
Video	see crash video



Dimensions & weight

Width	1999 mm
Height	1658 mm
Length	4688 mm
Wheel base	2865 mm
Kerb weight	1773 kg
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2
Engine number 2647315