



Mercedes-Benz



AV55HGJ

report date: 2024-03-29

General information

Make	MERCEDES
Model	B-CLASS B180 CDI SE
Colour	Blue
Year of manufacture	2005
Top speed	111 mph
0 - 60 mph	11.8 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	107 BHP
Max. torque	250 Nm at 2.600 rpm
Engine capacity	1.992 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-08-18
Pictures	32
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-04
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-24
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	47
Total items failed	10

MOT #21	2023-10-27 15:26
MOT test number	433928414909
Result	✓ Passed
Next expiry date	2024-11-24

MOT #20	2023-10-18 10:04
MOT test number	743266719052
Result	✗ Failed
Fail	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Fail	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Fail	Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #19**

2022-11-25 12:07

MOT test number

306615234998

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.2.2 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #18

2021-11-23 14:23

MOT test number

802041129612

Result

✓ Passed

**MOT #17**

2021-11-16 16:55

MOT test number

451637495488

Result

✗ Failed

Fail Central Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** General corrosion at rear**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**MOT #16**

2020-10-14 15:15

MOT test number

358985388281

Result

✓ Passed

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #15**

2020-10-14 09:59

MOT test number

152397576513

Result**✗ Failed**

- Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Front Lower Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14

2019-10-07 08:14

MOT test number

787978784391

Result**✓ Passed**

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Brake pipe corroded, covered in grease or other material FRONT TO REAR AT REAR (1.1.11 (c))

MOT #13

2018-10-25 09:20

MOT test number

323185871736

Result**✓ Passed**

- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #12** 2017-10-31 12:07**MOT test number** 696044123056**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #11** 2016-10-25 14:16**MOT test number** 608673893776**Result** ✓ Passed**MOT #10** 2015-10-30 14:18**MOT test number** 121384714281**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit 2.5mm aprox & outer areas worn thin (4.1.E.1)**Advice** Undertrays fitted**Advice** Offside Front Tyre worn close to the legal limit 3mm aprox & inner area worn thin (4.1.E.1)**Advice** Nearside Front tyre tread cracking

**MOT #9** 2015-10-26 14:16**MOT test number** 185931695531**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit 2.5mm aprox & outer areas worn thin (4.1.E.1)**Advice** Nearside Front tyre tread cracking**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Tyre worn close to the legal limit 3mm aprox & inner area worn thin (4.1.E.1)**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Advice** Undertrays fitted**Advice** FUEL filler pipes corroded**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2014-10-28 09:58**MOT test number** 529091804396**Result** ✓ Passed**MOT #7** 2014-10-28 09:58**MOT test number** 778661704329**Result** ✗ Failed**Pass with rectification** Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #6** 2013-10-31 09:15**MOT test number** 259444003306**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)



MOT #5	2012-10-15 09:52
---------------	------------------

MOT test number	339139782261
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2011-10-19 08:55
---------------	------------------

MOT test number	106772791206
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2010-04-13 08:42
---------------	------------------

MOT test number	290283300498
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

MOT #2	2009-09-02 09:02
---------------	------------------

MOT test number	134615349248
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2008-08-15 10:02
---------------	------------------

MOT test number	380488628247
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

X

Untaxed

Tax expired:
18 December 2023

✓

MOT

Expires:
24 November 2024

Tax status	Expired at 18 December 2023
Days left	133 days too late
MOT expiry date	24 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history


For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-09-15
Last registration	2023-10-27
Complete history	See info



Registration #1	2005-09-15	16 mi
Registration #2	2008-08-15	12.137 mi
Registration #3	2009-09-02	20.287 mi
Registration #4	2010-04-13	25.354 mi
Registration #5	2011-10-19	36.743 mi
Registration #6	2012-10-15	45.639 mi
Registration #7	2013-10-31	53.453 mi
Registration #8	2014-10-28	61.495 mi
Registration #9	2015-10-26	68.352 mi
Registration #10	2015-10-30	68.385 mi
Registration #11	2016-10-25	74.753 mi
Registration #12	2017-10-31	79.716 mi
Registration #13	2018-10-31	85.179 mi
Registration #14	2019-10-31	90.642 mi
Registration #15	2020-10-31	96.105 mi
Registration #16	2021-10-31	101.568 mi
Registration #17	2022-10-31	107.031 mi
Registration #18	2023-10-31	112.494 mi
Registration #19	2024-03-29	117.957 mi
Registration #20	2024-03-29	117.957 mi
Registration #21	2024-03-29	117.957 mi
Registration #22	2024-03-29	117.957 mi
Registration #23	2024-03-29	117.957 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64094030143072