



HY100UO

report date: 2024-03-28

General information

Make	FORD
Model	FIESTA ZETEC
Colour	Green
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-21
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	16
Total items failed	14

MOT #16	2024-01-22 14:31
MOT test number	578161685911
Result	✓ Passed
Next expiry date	2025-01-21
Advice	Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #15	2023-01-16 17:32
MOT test number	863954163894
Result	✓ Passed

MOT #14	2023-01-14 11:07
MOT test number	803702872456
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #13	2022-01-11 17:14
MOT test number	139224737422
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**MOT #12** 2022-01-11 14:47**MOT test number** 727332945820**Result** ✗ Failed**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Horn sound not in accordance with requirements (7.7 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MOT #11** 2021-01-19 14:09**MOT test number** 871216431265**Result** ✓ Passed**Advice** Nearside Rear Inner wheel rim distorted**MOT #10** 2020-03-04 08:16**MOT test number** 800389184575**Result** ✓ Passed**Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated on both sides. (5.3.4 (b) (i))**MOT #9** 2019-03-07 13:27**MOT test number** 416726503204**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #8** 2019-02-27 10:58**MOT test number** 695585119467**Result** ✗ Failed**Fail** Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure in tread area (5.2.3 (d) (ii))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Horn not working (7.7 (a) (ii))**Fail** Nearside Front Tyre not fitted in accordance with side wall instructions directional (5.2.3 (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #7** 2018-03-05 14:13**MOT test number** 773877233311**Result** ✓ Passed**Advice** Road wheel with a slightly distorted bead rim nearside rear and offside rear (4.2.A.1a)**MOT #6** 2018-02-27 08:40**MOT test number** 212916902631**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Road wheel with a slightly distorted bead rim nearside rear and offside rear (4.2.A.1a)**Fail** Front position lamp(s) not working nearside front (1.1.A.3b)**Fail** Tyre tread depth below requirements of 1.6mm offside front (4.1.E.1)**MOT #5** 2017-03-01 17:06**MOT test number** 690923420863**Result** ✓ Passed

**MOT #4** 2016-02-29 16:50**MOT test number** 622424575197**Result** ✓ Passed**Advice** Road wheel with a slightly distorted bead rim nearside rear and offside rear (4.2.A.1a)**Advice** Seat belt anchorage prescribed area is distorted but not considered excessive nearside outer sill (5.2.6)**MOT #3** 2014-07-14 09:12**MOT test number** 327185094140**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #2** 2014-06-30 17:58**MOT test number** 987701584104**Result** ✗ Failed**Fail** Horn not working (1.6.2a)**Notice** Items removed from driver's view prior to test**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #1** 2013-04-10 13:48**MOT test number** 715390603178**Result** ✓ Passed**Notice** Nearside front and nearside rear wheel rims buckled



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
21 January 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-25
Last registration	2024-01-22
Complete history	See info



Registration #1	2010-03-25	9 mi
Registration #2	2013-04-10	34.775 mi
Registration #3	2014-06-30	44.625 mi
Registration #4	2014-07-14	44.991 mi
Registration #5	2016-02-29	61.808 mi
Registration #6	2017-03-01	71.649 mi
Registration #7	2018-02-27	81.640 mi
Registration #8	2018-03-05	81.777 mi
Registration #9	2019-02-27	91.029 mi
Registration #10	2019-03-29	91.377 mi
Registration #11	2019-04-29	91.725 mi
Registration #12	2019-05-29	92.073 mi
Registration #13	2019-06-29	92.421 mi
Registration #14	2019-07-29	92.769 mi
Registration #15	2019-08-29	93.117 mi
Registration #16	2019-09-29	93.465 mi
Registration #17	2019-10-29	93.813 mi
Registration #18	2019-11-29	94.161 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1722 mm
Height	1433 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1109 kg
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	9E46444
---------------	---------