



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2022-07-01
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-21
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	24
Total items failed	6

MOT #16 2023-09-05 11:09

MOT test number 391396751565

Result ✓ Passed

Next expiry date 2024-09-21

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #15 2023-09-04 11:46

MOT test number 301773348673

Result ✗ Failed

Fail Nearside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Headlamp aim too low (4.1.2 (a))

MOT #14 2022-09-22 08:24

MOT test number 828837285300

Result ✓ Passed

**MOT #13** 2022-04-07 08:41**MOT test number** 611198255213**Result** ✓ Passed**MOT #12** 2021-12-17 13:27**MOT test number** 429600221738**Result** ✓ Passed**MOT #11** 2021-12-16 16:28**MOT test number** 446105910752**Result** ✗ Failed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2020-12-18 16:29**MOT test number** 875195509614**Result** ✓ Passed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #9** 2019-04-09 15:54**MOT test number** 510312058108**Result** ✓ Passed**MOT #8** 2019-04-09 12:06**MOT test number** 167602043089**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))



MOT #7	2018-04-13 08:48
---------------	------------------

MOT test number	632838161608
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2017-04-06 08:30
---------------	------------------

MOT test number	646832457179
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2016-03-21 16:03
---------------	------------------

MOT test number	368377555607
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2015-03-18 09:23
---------------	------------------

MOT test number	719987175011
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
---------------	--

Advice	Rear Brake pad(s) wearing thin (3.5.1g)
---------------	---

Notice	Engine covers fitted obscuring some components in the engine bay
---------------	--

Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

Advice	Front Brake pad(s) wearing thin (3.5.1g)
---------------	--

Notice	Under-trays fitted obscuring some underside components
---------------	--

**MOT #3** 2015-03-17 11:24**MOT test number** 759276475079**Result** ✗ Failed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2014-04-07 14:44**MOT test number** 347987094005**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #1 2013-04-09 14:35**MOT test number** 629979293059**Result** ✓ Passed

- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
21 September 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-04-14
Last registration	2023-09-05
Complete history	See info



Registration #1	2010-04-14	15 mi
Registration #2	2013-04-09	23.178 mi
Registration #3	2014-04-07	30.333 mi
Registration #4	2015-03-17	35.671 mi
Registration #5	2015-03-18	35.762 mi
Registration #6	2016-03-21	42.925 mi
Registration #7	2017-04-06	51.489 mi
Registration #8	2018-04-13	57.354 mi
Registration #9	2019-04-09	59.749 mi
Registration #10	2020-04-09	61.377 mi
Registration #11	2021-04-09	63.377 mi
Registration #12	2022-04-09	65.377 mi
Registration #13	2023-04-09	67.377 mi
Registration #14	2024-04-09	69.377 mi
Registration #15	2025-04-09	71.377 mi
Registration #16	2026-04-09	73.377 mi
Registration #17	2027-04-09	75.377 mi
Registration #18	2028-04-09	77.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602