






report date: 2024-03-29

General information

Make	PEUGEOT
Model	EXPERT E7 TAXI
Colour	Black
Year of manufacture	-
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	270 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	40.4 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-09-19

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT #9 2021-11-16 14:02

MOT test number 179067824895

Result
✓ Passed

Next expiry date 2022-11-15

Advice Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced outersill (6.1.1 (c) (i))

butersiii (6.1.1 (C) (i)

Advice Underside of vehicle is undersealed heavy cant determined the quality of repaiars and condition

MOT #8 2016-02-24 10:08

MOT test number 298562875602

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Corrosion around gear box mounting (upper)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Step in contact with fuel tank

Advice Offside Front Suspension component mounting prescribed area is corroded but not considered

excessive (2.4.A.3)

Advice Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement both bushes

worn (2.4.G.2)

Advice Oil leak

CarCheck.co.uk page 3/12



report date: 2024-03-29

228897135258

MOT #7 2016-02-16 11:59

MOT test number 867121264212

Result X Failed

Fail Centre Exhaust has a major leak of exhaust gases (7.1.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Oil leak

Fail Offside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

Advice Corrosion around gear box mounting (upper)

Advice Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement both bushes worn (2.4.G.2)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Suspension component mounting prescribed area is corroded but not considered

excessive (2.4.A.3)

MOT test number

Advice Step in contact with fuel tank

MOT #6 2015-08-25 11:52

Result ✓ Passed

MOT #5 2015-02-25 12:57

MOT test number 698846055043

Notice O/s/f door check strap worn

Notice Small cut in the tread of the n/s/f tyre that doesnt reach cords

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4 2015-02-25 12:57 **MOT** test number 285146155034 Result **X** Failed **Notice** O/s/f door check strap worn Pass with rectification Offside Front Headlamp insecure (1.7.3) Pass with rectification Offside Front Windscreen wiper blade insecure (8.2.2) Notice Small cut in the tread of the n/s/f tyre that doesnt reach cords Pass with rectification Nearside Front Windscreen wiper blade insecure (8.2.2)

MOT #3 2014-09-09 13:13 425592054293 **MOT** test number Result ★ Failed Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2) Fail Upper Stop lamp not working (1.2.1b) Brake pedal anti-slip provision missing (3.3.A.1b) Fail **Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2) **Notice** Exhaust mounting bolts not holding exhaust sections together firm enought Fail Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2) Fail Offside Rear Registration plate lamp not working (1.1.C.1d) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) **Notice** N/s/f fog light inop

MOT #2	2009-05-29 14:00
MOT test number	644969149158
Result	✓ Passed
Advice Offside Suspension arm has slight play in a pin/bush (2.4.G.2)	

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT #1 2009-04-03 11:12

MOT test number 372163499093

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner	history
-------	---------

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

THE STREET STREE	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	UK ZIS
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2006-06-14
Last registration	2021-11-16
Complete history	See info



Registration #1	2006-06-14	28 mi
Registration #2	2009-04-03	153.150 mi
Registration #3	2009-05-29	154.441 mi
Registration #4	2014-09-09	162.116 mi
Registration #5	2015-02-25	172.656 mi
Registration #6		71.777 66
Registration #7		0.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1927 mm
Length	4440 mm
Max. allowed weight	2505 kg

Additional information

Number of seats	8
Number of axles	2
Engine number	DYSX4024205

CarCheck.co.uk page 12/12