





report date: 2024-03-28

General information

Make	FIAT
Model	TIPO LOUNGE
Colour	Red
Year of manufacture	2017
Top speed	115 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-13

Pictures 34

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-07-04
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	23
Total items failed	0

MOT #8	2023-07-05 12:59
MOT test number	319245951560
Result	✓ Passed
Next expiry date	2024-07-04

MOT #7	2023-06-30 09:00
MOT test number	432559934008
Result	× Failed
MAJOR Offside Front Coil spring fractured or broken (5.3.1	L (b) (i))

MOT #6	2023-06-02 10:28

MOT test number 707942253795

Result X Failed

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5		2022-07-02 08:25
MOT test	number	970329126155
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 1.8mm (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.0mm (5.2.3 (e))		

MOT #4		2021-06-07 15:48
MOT test	number	107655234942
Result		✓ Passed
MOT #3		2020-12-05 10:45
MOT test	number	380318395907
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively both (1.1.14 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2 2020-11-30 17:13 588927423758 **MOT** test number Result × Failed **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Front Brake disc worn, but not excessively both (1.1.14 (a) (i)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) MAJOR Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice **Advice** Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))

MOT #1 2019-11-18 15:06

MOT test number 167281353509

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

*		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report $\underline{\underline{F}}$		e?

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12





report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-03-30
Last registration	2023-07-05
Complete history	See info



Registration #1	2017-03-30	11 mi
Registration #2	2019-11-18	32.168 mi
Registration #3	2020-11-30	43.740 mi
Registration #4	2020-12-05	43.854 mi
Registration #5	2021-06-07	46.570 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.77 es
•		11.777 ea 11.777 ea 11.777 ea
Registration #7		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1270 kg
Max. allowed weight	1695 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles2Engine number2240577