

# **\$** SUZUKI



## General information

Make SUZL	IKI
Model SPLA	SH SZ3
Colour White	2
Year of manufacture2012	
Top speed99 m	ph
<b>0 - 60 mph</b> 14.7	seconds
Gearbox 5 spe	eed Manual

# Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 4.800 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	В








## Internet history

Entry 2	
Date	2022-02-27
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1	
Date	2021-02-04
Pictures	1
Listing price	View report



source: autoonline.co.uk



# MOT history

MOT expiry date	2025-01-17
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	27
Total items failed	6

MOT #11 2	2024-01-14 12:55
MOT test number	766154615003
Result	✓ Passed
Next expiry date	2025-01-17
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #10	2023-01-11 13:26
MOT test number	352519974065
Result	✓ Passed
Advice Central Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #9	2022-01-18 11:17
MOT test number	344957060897
Result	✓ Passed
Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice Offside Rear Service brake grabbing slightly (1.2.1 (c))	
Advice Brake pedal wearing smooth (1.1.2 (c))	





MOT #8	2022-01-06 15:46
MOT test number	929342534827
Result	🗙 Failed
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
<b>Fail</b> Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
<b>Fail</b> Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
<b>Fail</b> Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Advice Offside Rear Service brake grabbing slightly (1.2.1 (c))	
Advice Brake pedal wearing smooth (1.1.2 (c))	

MOT #7	2021-01-06 16:38
MOT test number	766199936189
Result	✓ Passed
<b>Advice</b> Front Brake pipe corroded, covered in grease or other material b corroded (1.1.11 (c))	ooth sides in wheelarches



SD62XXU
report date: 2024-03-29

MOT #6	2021-01-04 16:59
MOT test number	763042657950
Result	🗙 Failed
Fail         Nearside Side repeater not working (4.4.1 (a) (ii))	
<b>Fail</b> Offside Rear Brake pipe excessively corroded by fuel tank (1.1.11 (c))	
Advice Front Brake pipe corroded, covered in grease or other material both sides in will corroded (1.1.11 (c))	heelarches
Minor Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))	
FailOffside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Nearside Rear Brake pipe corroded, covered in grease or other material by fue (1.1.11 (c))	l tank corroded
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Minor Offside Windscreen wiper blade defective (3.4 (b) (i))	

MOT #5	2019-07-02 09:44
MOT test number	492126274669
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.	14 (a) (ii))
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive mo bush (5.3.4 (a) (i))	ovement back
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))
(i)) Offside Registration plate lamp inoperative in the case of multiple lamps or light s	sources (4.7.1 (b)
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive n bush (5.3.4 (a) (i))	novement back
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #4	2018-07-10 10:03
MOT test number	406234697001
Result	✓ Passed
Advice Offside Front Suspension arm pin or bush worn but not resulting in exback bush (5.3.4 (a) (i))	xcessive movement wishbone
Advice Offside Front Brake disc worn, pitted or scored, but not seriously wea	akened (1.1.14 (a) (ii))
<b>Advice</b> Nearside Front Suspension arm pin or bush worn but not resulting in wishbone back bush (5.3.4 (a) (i))	excessive movement
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously we	eakened (1.1.14 (a) (ii))

MOT #3	2017-07-11 12:43
MOT test number	522527384428
Result	✓ Passed
MOT #2	2016-09-02 16:27
MOT test number	167256778850
Result	✓ Passed
MOT #1	2015-09-09 14:40

MOT test number		

Result

649967675126

🗸 Passed



Tax & MOT check

<b>Tax due:</b> 1 March 2025	✓ Taxed	<b>Expires:</b> 17 January 2025	✓ МОТ
Tax status			Valid until 1 March
Days left			306
MOT expiry date			17 January 2025
Full MOT history			<u>See MOT history</u>
Tax calculation			

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





### Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

#### Extra SUZUKI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





## Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
*********	
********	
*******	
*********	
********	
	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carried registration	
Falls since	





### Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-29
Last registration	2024-01-14
Complete history	See info



Registration #1	2012-09-29	23 mi
Registration #2	2015-09-09	23.556 mi
Registration #3	2016-09-02	34.183 mi
Registration #4	2017-07-11	47.034 mi
Registration #5	2018-07-10	52.979 mi
Registration #6	2019-07-02	60.585 mi
Registration #7	2021-01-04	62.308 mi
Registration #8		11.777 esi
Registration #9		11.777 est
Registration #9 Registration #10		11.227 est
		01,000 est 01,000 est 01,000 est
Registration #10		01,000 est 01,000 est 01,000 est 01,000 est
Registration #10 Registration #11		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est





Safety ratings

NCAP rating

Video

\*\*\*\*

see crash video



Dimensions & weight	
Width	1680 mm
Height	1590 mm
Length	3775 mm
Wheel base	2360 mm
Kerb weight	1075 kg
Max. allowed weight	1485 kg
Additional information	
Additional information Fuel tank capacity	45 I
	45 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5