



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	EXPERT HDI 1200 L2H1 P/V
Colour	White
Year of manufacture	2014
Top speed	90 mph
0 - 60 mph	17.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-10-14
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-27
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	15
Total items failed	3

MOT #11	2023-10-16 15:52
MOT test number	922190601154
Result	✓ Passed
Next expiry date	2024-10-27
Advice	Power steering component has slight seepage from a component Rack (2.1.5 (a))

MOT #10	2023-10-07 08:53
MOT test number	559700671970
Result	✗ Failed
MAJOR	Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
DANGEROUS	Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
MAJOR	Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
DANGEROUS	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Power steering component has slight seepage from a component Rack (2.1.5 (a))

**MOT #9** 2022-10-22 07:42**MOT test number** 844496598052**Result** ✓ Passed**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**MOT #8** 2021-10-22 07:57**MOT test number** 689611312344**Result** ✓ Passed**MOT #7** 2020-10-10 10:10**MOT test number** 323928799446**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2020-10-10 10:10**MOT test number** 896811920028**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #5** 2019-10-12 08:14**MOT test number** 385905220484**Result** ✓ Passed

**MOT #4** 2019-10-12 08:14**MOT test number** 443574108895**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #3** 2018-10-20 11:01**MOT test number** 770421379327**Result** ✓ Passed**MOT #2** 2018-10-20 08:01**MOT test number** 570383270854**Result** ✗ Failed**MAJOR** Offside Front Position lamp not working (4.2.1 (a))**DANGEROUS** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #1** 2017-10-09 15:30**MOT test number** 546623172244**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-10-28
Last registration	2023-10-16
Complete history	See info



Registration #1	2014-10-28	24 mi
Registration #2	2017-10-09	35.237 mi
Registration #3	2018-10-20	46.829 mi
Registration #4	2018-10-20	46.832 mi
Registration #5	2019-10-12	62.081 mi
Registration #6	2019-10-12	62.081 mi
Registration #7	2020-10-10	69.727 mi
Registration #8	2020-10-10	69.727 mi
Registration #9	2020-10-10	69.727 mi
Registration #10	2020-10-10	69.727 mi
Registration #11	2020-10-10	69.727 mi
Registration #12	2020-10-10	69.727 mi
Registration #13	2020-10-10	69.727 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	2194 mm
Height	1980 mm
Length	5135 mm
Kerb weight	1800 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	JBDF0056164