



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D2 ES
Colour	Black
Year of manufacture	2013
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 2.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-25
Pictures	26
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-06
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	17
Total items failed	2

MOT #13	2024-04-05 09:10
MOT test number	517717303332
Result	✓ Passed
Next expiry date	2025-04-06

MOT #12	2023-04-07 15:28
MOT test number	731420166833
Result	✓ Passed

MOT #11	2023-04-07 15:28
MOT test number	688003671555
Result	✗ Failed

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #10	2022-06-24 12:22
MOT test number	112166233469
Result	✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2022-06-24 12:22**MOT test number** 670740709035**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #8** 2021-06-25 17:17**MOT test number** 323852701366**Result** ✓ Passed**MOT #7** 2020-09-04 14:44**MOT test number** 632631765409**Result** ✓ Passed**MOT #6** 2020-09-02 10:40**MOT test number** 366660567135**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #5** 2019-09-03 12:10**MOT test number** 740145795149**Result** ✓ Passed

**MOT #4** 2018-09-07 10:41**MOT test number** 566344476801**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #3** 2017-09-05 09:45**MOT test number** 394592984713**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Under Trays Fitted Obscuring Some Under Side Components**MOT #2** 2016-09-12 16:00**MOT test number** 296489422985**Result** ✓ Passed**MOT #1** 2016-08-12 10:37**MOT test number** 489970798472**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Engine and underside covers fitted not allowing full inspection**Advice** Both front tyres wearing on inner tread



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
6 April 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	6 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-08-15
Last registration	2024-04-05
Complete history	See info



Registration #1	2013-08-15	24 mi
Registration #2	2016-08-12	80.450 mi
Registration #3	2016-09-12	80.816 mi
Registration #4	2017-09-05	88.088 mi
Registration #5	2018-09-07	95.380 mi
Registration #6	2019-09-03	101.953 mi
Registration #7	2020-09-02	107.289 mi
Registration #8	2020-09-04	107.291 mi
Registration #9	2021-09-03	112.625 mi
Registration #10	2022-09-02	117.959 mi
Registration #11	2023-09-01	123.293 mi
Registration #12	2024-04-05	128.627 mi
Registration #13	2024-04-05	128.627 mi
Registration #14	2024-04-05	128.627 mi
Registration #15	2024-04-05	128.627 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1602 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	4147420
---------------	---------