



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SEL TDI
Colour	Blue
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	195 Nm at 1.500 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	76.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-06-09
Pictures	27
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-13
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	14
Total items failed	12

MOT #14	2023-10-12 14:48
MOT test number	272137235280
Result	✓ Passed
Next expiry date	2024-10-13

MOT #13	2022-10-06 13:54
MOT test number	243859320505
Result	✓ Passed
Advice	Front and rear suspension has surface corrosion
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #12**

2022-10-06 10:51

MOT test number

521090922981

Result**✗ Failed****Advice**

Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Fail

Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice

Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Fail

Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice

Front and rear suspension has surface corrosion

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail

Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #11

2021-10-13 10:11

MOT test number

954304077193

Result**✓ Passed****MOT #10**

2020-10-14 09:59

MOT test number

912226972172

Result**✓ Passed**

**MOT #9** 2020-10-08 15:13**MOT test number** 352796327927**Result** ✗ Failed

- Advice** Exhaust has a minor leak of exhaust gases deteriorated (6.1.2 (a))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #8 2019-05-09 08:43**MOT test number** 327034565559**Result** ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both rears (1.1.14 (a) (ii))

MOT #7 2018-06-01 15:08**MOT test number** 507735645558**Result** ✓ Passed

**MOT #6** 2018-05-30 13:04**MOT test number** 570196721491**Result** ✗ Failed**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Front discs corroded -**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Rear suspension bump stops deteriorated**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))**MOT #5** 2017-04-25 16:19**MOT test number** 264758333335**Result** ✓ Passed**MOT #4** 2016-05-06 14:04**MOT test number** 289595720647**Result** ✓ Passed**MOT #3** 2015-04-23 15:02**MOT test number** 356083115143**Result** ✓ Passed**MOT #2** 2014-04-25 14:23**MOT test number** 905945914176**Result** ✓ Passed



MOT #1	2013-04-15 12:01
MOT test number	279535603419
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
13 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	13 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-04-27
Last registration	2023-10-12
Complete history	See info



Registration #1	2010-04-27	27 mi
Registration #2	2013-04-15	25.281 mi
Registration #3	2014-04-25	34.922 mi
Registration #4	2015-04-23	40.432 mi
Registration #5	2016-05-06	46.950 mi
Registration #6	2017-04-25	50.113 mi
Registration #7	2018-05-30	55.937 mi
Registration #8	2018-06-01	55.974 mi
Registration #9	2019-05-29	55.977 mi
Registration #10	2019-05-29	55.977 mi
Registration #11	2019-05-29	55.977 mi
Registration #12	2019-05-29	55.977 mi
Registration #13	2019-05-29	55.977 mi
Registration #14	2019-05-29	55.977 mi
Registration #15	2019-05-29	55.977 mi
Registration #16	2019-05-29	55.977 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

CAY 041769