

Ford



### General information

| Make                | FORD                      |  |
|---------------------|---------------------------|--|
| Model               | S-MAX TITANIUM SPORT TDCI |  |
| Colour              | Black                     |  |
| Year of manufacture | 2016                      |  |
| Top speed           | 135 mph                   |  |
| 0 - 100 km/h        | 9.5 seconds               |  |
| 0 - 60 mph          | 8.8 seconds               |  |
| Gearbox             | 6 speed automatic         |  |

# Engine & fuel consumption

| Power                   | 132 kW / 180 HP / 207 BHP |
|-------------------------|---------------------------|
| Max. torque             | 400 Nm at 1.750 rpm       |
| Engine capacity         | 1.997 cc                  |
| Cylinders               | 4                         |
| Fuel type               | Diesel                    |
| Consumption city        | 44.8 mpg                  |
| Consumption extra urban | 55.4 mpg                  |
| Consumption combined    | 51.4 mpg                  |
| CO2 emission            | 129 g/km                  |
| CO2 label               | D                         |





| Internet history |             |
|------------------|-------------|
| Entry 1          |             |
| Date             | 2021-01-31  |
| Pictures         | 1           |
| Listing price    | View report |



source: autoonline.co.uk



## MOT history

| MOT expiry date    | 2024-11-02 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 5          |
| Failed MOT tests   | 0          |
| Total advice items | 6          |
| Total items failed | 0          |

| MOT #5           | 2023-10-30 10:13 |
|------------------|------------------|
| MOT test number  | 843620912726     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-11-02       |

| MOT #4   | 2022-10-13 08:55 |
|--|------------------|
| MOT test number  | 179834223906     |
| Result   | ✓ Passed         |
| Advice Nearside Oil leak, but not excessive high pressure fuel pump area (8.4.1 (a) (i)) |                  |

| MOT #3   |  | 2021-10-29 10:09 |
|----------|--|------------------|
| MOT test | number   | 202184792553     |
| Result   |  | ✓ Passed         |
| Minor    | Offside Front Windscreen wiper blade defective (3.4 (b) (i)) |                  |
| Advice   | Nearside Rear Nail in tyre                                   |                  |
|          |  |                  |

| MOT #2          | 2020-11-03 15:21 |
|-----------------|------------------|
| MOT test number | 943382964606     |
| Result          | ✓ Passed         |





| MOT #1  | 2019-07-24 10:04 |
|---|------------------|
| MOT test number   | 399008159039     |
| Result  | Passed           |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))            |                  |
| Advice Child Seat fitted not allowing full inspection of adult belt |                  |
| Advice Items removed from driver's view prior to test               |                  |



Tax & MOT check

| ✓<br>Taxed<br><sup>Tax due:</sup> | ✓<br>MOT<br>Expires:                   |
|-----------------------------------|--|
| 1 March 2025<br>Tax status        | 2 November 2024<br>Valid until 1 March |
| Days left                         | 306                                    |
| MOT expiry date                   | 2 November 2024                        |
| Full MOT history                  | See MOT history                        |

## Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | D          |
| Single payment (12 months)              | £ 150,00,- |
| Single six month payment                | £ 82,50,-  |
| Total payable by 12 monthly instalments | £ 157,50,- |





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |  |       |
|----------|--|-------|
| Date     | F  |       |
| Category |  | ARME  |
| Туре     |  |       |
| Damage 2 |  | AMPLE |
|          | E E  |       |
| Date     |  | \$    |
| Category | AMP  |       |
| Туре     | No. Contraction of the second se |       |

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec |             |
|--|-------------|
| ************   |             |
| *******  |             |
| *******  |             |
| ***********  |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this FORD had different number plates.  |             |
| Number of plates   | ,           |
| Current registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  |             |





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |


More info  $\rightarrow$ 





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 7          |
| First mileage registration | 2016-09-27 |
| Last registration          | 2023-10-30 |
| Complete history           | See info   |



| Registration #1 | 2016-09-27 | 25 mi      |
|-----------------|------------|------------|
| Registration #2 | 2019-07-24 | 23.770 mi  |
| Registration #3 | 2020-11-03 | 32.297 mi  |
| Registration #4 |            | 11.777 esi |
| Registration #5 |            | 11.777 mi  |
| Registration #6 |            | 11.777 est |
| Registration #7 |            | 11.777 mi  |

More info >





## Car features

| S0225  | Air conditioning |
|--------|------------------|
| \$0295 |                  |
| S0482  |                  |
| \$0501 |                  |
| S0566  |                  |
| S0567  |                  |
| S0569  |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 87%             |
| Children       | 87%             |
| Pedestrian     | 79%             |
| Safety systems | 71%             |
| Overall rating | 82%             |
| Video          | see crash video |



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 2137 mm          |
| Height                            | 1655 mm          |
| Length                            | 4796 mm          |
| Wheel base                        | 2849 mm          |
| Kerb weight                       | 1626 kg          |
| Max. allowed weight               | 2535 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 70               |
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 5                |
| Number of axles<br>CarCheck.co.uk | 2 page 11/11     |