





report date: 2024-03-28

#### General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Purple
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2021-09-26

Pictures 25

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



CE63UHF report date: 2024-03-28

MOT history

MOT expiry date	2024-07-08
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #10	2023-07-04 13:16	
MOT test number	218929602580	
Result	✓ Passed	
Next expiry date 2024-07-		
Advice Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))		

MOT #9		2022-07-08 13:28
MOT test	number	928080771776
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge close to limit (5.2.3 (e	))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #8	2021-07-07 10:38
MOT test number	390018287477
Result	✓ Passed
Advice Offside Front Anti-roll bar linkage pin or bush worn but not result (a) (i))	ulting in excessive movement (5.3.4
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Nearside Front Service brake binding but not excessively (1.2.	1 (f))

CarCheck.co.uk page 3/12



Result

CE63UHF

report date: 2024-03-28

✓ Passed

 MOT #7
 2020-07-09 12:38

 MOT test number
 340817090343

**Result** 
✓ Passed

MOT #6 2020-07-09 09:17

MOT test number 889362244062

Result X Failed

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Offside Front Brake disc significantly and obviously worn inner face (1.1.14 (a) (i))

Fail Nearside Front Brake disc significantly and obviously worn inner face (1.1.14 (a) (i))

MOT #5 2019-08-12 09:23

**MOT test number** 888286235237

Minor Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2019-08-12 09:23

MOT test number 856575608468

**Result** X Failed

Minor Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #3 2018-08-19 11:21

**MOT test number** 473688228037

Result 

Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2	2017-09-25 12:06
MOT test number	355372721283
Result	<b>✓</b> Passed
MOT #1	2016-09-26 08:43
MOT test number	665530558988
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	8 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

# Owner history

Owner mistory		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is		GEOT
********		
***************************************		
*********		
************		
	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	OK SIE	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >


CarCheck.co.uk page 10/12



CE63UHF report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-30
Last registration	2023-07-04
Complete history	See info



Registration #1	2013-09-30	18 mi
Registration #2	2016-09-26	10.859 mi
Registration #3	2017-09-25	15.109 mi
Registration #4	2018-08-19	19.008 mi
Registration #5	2019-08-12	27.623 mi
Registration #6	2019-08-12	27.623 mi
Registration #7		11.777 es
Registration #8		111,7177 ess
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.117 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	***
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



## Dimensions & weight

Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12