





report date: 2024-03-28

### General information

Make	TOVOTA
Make	TOYOTA
Model	AYGO VVT-I X-PLAY
Colour	White
Year of manufacture	2016
Top speed	99 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	69 BHP
Max. torque	95 Nm at 4.300 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	56.5 mpg
Consumption extra urban	78.5 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history


### Entry 1

Date 2021-05-26


Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



YD66SXB report date: 2024-03-28

MOT history

MOT expiry date	2024-05-15
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	19
Total items failed	1

MOT #6		2023-05-15 08:26
MOT test	number	735595064158
Result		✓ Passed
Next expi	ry date	2024-05-15
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice (a) (i))	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in ex	ccessive movement (5.3.4
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Advice Nearside Rear Nail in tyre	
Advice	Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT #5** 2022-05-16 15:50

**MOT test number** 835906612152

**Result** ✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement bush at rear splitting (5.3.4 (a) (i))

**Advice** Nearside Front Tyre slightly damaged sidewall (5.2.3 (d) (ii))

**Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement rubber bushes worn (5.3.4 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement bush at rear splitting (5.3.4 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement rubber bushes worn (5.3.4 (a) (i))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #4 2021-05-15 11:34

MOT test number 159358638273

Result \( \sqrt{Passed} \)

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3 2020-09-16 17:00

MOT test number 901918135964

Result \( \sqrt{Passed} \)

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Tyre sidewall perished (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

643816579865

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake lining(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Brake lining(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Tyre sidewall perished (5.2.3 (d) (ii))

 MOT #1
 2019-08-27 14:34

 MOT test number
 224014144053

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



YD66SXB report date: 2024-03-28

# Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	15 May 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Vehicle Class	40
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



furthe scinors

YD66SXB

report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this TOYOTA had different number plates.

CarCheck.co.uk page 9/12



YD66SXB report date: 2024-03-28

### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-09-20
Last registration	2023-05-15
Complete history	See info



Registration #1	2016-09-20	17 mi
Registration #2	2019-08-27	53.489 mi
Registration #3	2020-09-16	74.452 mi
Registration #4	2020-09-16	74.452 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		0.77

More info >

page 11/12 CarCheck.co.uk



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	80%
Children	80%
Pedestrian	62%
Safety systems	56%
Overall rating	72%
Video	see crash video



# Dimensions & weight

Width	1615 mm
Height	1460 mm
Length	3455 mm
Wheel base	2340 mm
Kerb weight	855 kg
Max. allowed weight	1240 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2

Engine number 1KR8195579