



RENAULT

UK

SKIWLA

report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO EXPRESSION VVT
Colour	Silver
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	12.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg





Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT #14	2022-09-13 17:51
MOT test number	944751619785
Result	✓ Passed
Next expiry date	2023-09-12

MOT #13	2022-09-13 16:50
MOT test number	426234204038
Result	✗ Failed

- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #12	2021-11-05 12:46
MOT test number	438935555302
Result	✓ Passed

- Advice** Front radiator bracket corroded
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #11	2020-11-06 09:19
MOT test number	613657544133
Result	✓ Passed

MOT #10	2020-03-10 13:38
MOT test number	866697354039
Result	✓ Passed

- Advice** Front cross member corroded
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2019-03-01 15:51

MOT test number

576442171528

Result

✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Bracket holding radiator corroded
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing nail in tyre (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8

2019-03-01 14:41

MOT test number

544404885138

Result

✗ Failed

- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Items removed from driver's view prior to test
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing nail in tyre (5.2.3 (d) (ii))
- Advice** Bracket holding radiator corroded

MOT #7

2018-02-27 12:26

MOT test number

264894566556

Result

✓ Passed

- Advice** Offside rear brake disc inner surface slightly deteriorated
- Advice** Both rear tyres perished and cracked on outer sidewalls

**MOT #6**

2017-03-09 09:11

MOT test number

959885301192

Result

✓ Passed

Advice

Rear brake disc modified but not seriously weakened both (3.5.1n)

Advice

Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

MOT #5

2016-03-16 11:57

MOT test number

903429627817

Result

✓ Passed

Advice

Both front tyres sidewalls perished cut in osf tyre sidewall

Advice

Osr wheel slightly binding

Advice

Rear discs corroded

Advice

Front registration plate faded but not likely to be misread (6.3.1d)

MOT #4

2016-03-15 16:28

MOT test number

567517172025

Result

✗ Failed

Advice

Front registration plate faded but not likely to be misread (6.3.1d)

Fail

Nearside Track rod end ball joint has excessive play (2.2.B.1f)

Advice

Both front tyres sidewalls perished cut in osf tyre sidewall

Advice

Osr wheel slightly binding

Fail

Rear registration plate faded (6.3.1d)

Fail

Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice

Rear discs corroded



MOT #3	2015-03-17 15:21
MOT test number	275186875038
Result	✓ Passed
Notice	Nsr h/brake cable cooroded caliper side
Notice	Osf tyre cuts to sidewall and heavily perished

MOT #2	2015-03-13 12:56
MOT test number	888022975034
Result	✗ Failed
Fail	Nearside Rear Shock absorber has a serious fluid leak (2.7.3)
Notice	Nsr h/brake cable cooroded caliper side
Notice	Osf tyre cuts to sidewall and heavily perished

MOT #1	2014-02-17 11:08
MOT test number	375458544054
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	SK11WLA
Plate since	2024-03-28
Current registration	SK11WLA
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-01
Last registration	2022-09-13
Complete history	See info



Registration #1	2011-03-01	25 mi
Registration #2	2014-02-17	3.511 mi
Registration #3	2015-03-13	6.645 mi
Registration #4	2015-03-17	6.647 mi
Registration #5	2016-03-15	10.813 mi
Registration #6	2016-03-16	10.813 mi
Registration #7	2017-03-09	14.551 mi
Registration #8	2018-02-27	19.777 mi
Registration #9	2019-05-20	25.277 mi
Registration #10	2019-05-20	25.277 mi
Registration #11	2019-05-20	25.277 mi
Registration #12	2019-05-20	25.277 mi
Registration #13	2019-05-20	25.277 mi
Registration #14	2019-05-20	25.277 mi
Registration #15	2019-05-20	25.277 mi
Registration #16	2019-05-20	25.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1720 mm
Height	1497 mm
Length	4032 mm
Wheel base	2575 mm
Kerb weight	1080 kg
Max. allowed weight	1675 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D041810